

Hobbs installed

AIRFRAME LOGS 1 of 53
(3 Log books.)

WHITE 83-508
Pac. BLUE 83-74902
BLACK 83-005

INTERIOR:
BLUE 246-57655

#1
NUMBER AF5

TC-157

COPYRIGHT 1945

BY

AIR ASSOCIATES, INC.

PRINTED IN U. S. A.

AIR ASSOCIATES INCORPORATED

TETERBORO, NEW JERSEY

ATLANTA, GA.
Atlanta Municipal Airport
Tel. Calhoun 1107

DALLAS, TEXAS
3214 Love Field Dr.
Tel. Dixon 4-2611

TETERBORO, N.J.
Teterboro Air Terminal
Hasbrouck Heights 8-1500

CHICAGO, ILL.
5315 W. 63rd St.
Tel. Portsmouth 7-2800

GLENDALE, CAL.
1231 Air Way
Tel. Citrus 4-4151

MIAMI, FLA.
P.O. Box 241
Int'l Airport
Tel. Miami 64-4567

AIRCRAFT DESCRIPTION

Manufacturer	BEECH AIRCRAFT CORP.		Place	WICHITA, KANS.	Date
License No.	N 1357 Z		Type	95-55	Serial No. TC-157
Description					
Reconstructed By			Place		Date
Seating Capacity (Crew Included)			Weight Empty	Weight Loaded	
Wing Area	Sq. Ft.	Control Area	Sq. Ft.	Span	Length
Tires Main	Tire Tail		Brakes		
Owner	Address				
City	State				

Propeller
Blade Des
Pitch
Engine
Rated H.
Receiver
Transmitte
Generator
Starter
Power Un

LICENSE NUMBER	DATE	REMARKS
		INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		REPLACE RUDDER With Factory New RUDDER. (Service Bulletin #11)
		J. R. Lucci A.A. A.P. 24914-40

LICENSE NUMBER	DATE	REMARKS
		INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
	2-5-62	Replaced left brake Assy. J. M. Eisenhatter M-256134

LICENSE NUMBER	NO.	Date of Compliance	MANUFACTURERS — C. A. A. BULLETINS
			REMARKS
		3-1-62	Installed Collins 618F-1 Transceiver, +270-1 Power Supply, 51X-3 Receiver, 344D-2 Impedance Converter, Motorola A.D.F. T-12, A.D.F. Indic- ator, loop, sense ant., M.B.L.-24 Marker Beacon, Collins 37X-2 Marker Antenna, Collins +27-B1 Power Supply, A.D.F. amplifier See 337 this date for details. New E.W. 3181.9 lbs. New E.W. C.T. 77.0 in aft. of datum New Useful Load - 1698.1 lbs. George H. Eisenhatter M-25613-40 for Atlantic Operation Serv. Div. International Airport, Phila. Pa.

REMARKS

LICENSE
NUMBER

DATE

INSPECTION - MAINTENANCE - REPA

3/20/62

tach Rd. 98 hr.

This Aircraft and/or component identified above was repaired and inspected in accordance with current Civil Air Regulations and was found airworthy for return to service.

Pertinent details of the repair are on file at this agency under work order No. 3247

Repair Station No. 287

Date 3/20/62 Signed *J. W. Zaleski*

Airframe Class 3

Limited Propeller

Limited Magnetic and Fluorescent Inspection.

Radio - Class 1 and Limited Radio

SB 248

3/20/62

98 HRS

Installed one zero Time factory overhaul
Continental engine, Model 10-470-L

S/N - 9200H1-L-R, on Right side

very good
AOG 1325932

C/W Service Bulletin #2 + 8.

REMARKS

E
LICENSE
NUMBER

DATE

INSPECTION - MAINTENANCE - REPAIRS - ALTERATIONS

ATLANTIC AVIATION SERVICE, Inc.
PHILADELPHIA INTERNATIONAL AIRPORT
PHILADELPHIA, PA.

I certify that this Aircraft ~~or Engine~~ has been inspected in accordance with a 100 Hour or Periodic inspection and determined to be in an airworthy condition.

3/2/62

Date

G. P. Lombardi 25013-48
Signature I.A., A&E, Repair Station

Total Airframe or Engine Time 92:15

order # 5648.

C/W Service Bulletin #7
(Eng mt. bolts) Installed
Winterization kit #55-13-1
Ser. #128. Inst. new left nose
gear door, torqued wing bolts,
new right brake housing disc,
blocks, clips. For preventative
maintenance done see A work

CB #7

winterization kit

55-13-1 553

TT 25 93.15 3/2/62

REMARKS

LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
8-2362		Installed new brake housings in both main wheels complete with new brake blocks and disks bleed Brake system. 261:55 Hrs R+P 1388076 Donald J Wall

REMARKS

LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
9/21/62		Installed both new main tires and all new brake pads. L. Maissenhalter DA #25013-40.
10-9-62		Installed a Directional Gyro, Artificial Horizon, Airspeed Indicator, Slidescope, Receiver. L. Maissenhalter DA #25013-40
10-9-62		Installed a Zep high press. oxygen system as per Beech drawing #55-001059 plus a pilot shut-off valve. L. Maissenhalter DA #25013-40 See 337 form this date for details.
10-9-62		Installed a dual control column Item 40246 New E.N. - 3242 lbs L. Maissenhalter New E.N.C.G. - 78.1 in aft of datum. DA #25013-40 for New Useful Load - 1638 lbs. At Landing (1st. Serv. Inc.

REMARKS

TURE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
			ATLANTIC AVIATION SERVICE, Inc. PHILADELPHIA INTERNATIONAL AIRPORT PHILADELPHIA, PA. I certify that this Aircraft and Engine has been inspected in accordance with a 100-Hour or Periodic inspection and determined to be in an airworthy condition. 10-9-62 Date J. Maisenhalter 25013-40 Signature I.A., A.C.E., Repair Station Total Airframe or Engine Time 298:52 Replaced cabin door lock Installed larger generator filters. Replaced one nose wheel bearing race and both cones. Serviced shimmy damp eners. C/w Service Bulletin #9 (10-62-8-3), #12, Service letter #4. For preventative maint. enance done, see AA work order # 6426.

REMARKS

IRE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		12-7-62	Installed 5th seat, replaced all brake blocks & clips J. Maisenhalter Id # 25013-40 for Atlantic Aviation Serv. Inc. Inter. Airport Phila. Pa.

REMARKS

RE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		2-15-63	Installed Prop Anti-icer kit 55-3-1 Ser. # 115. See 337 form this date for details. J. Maisenhalter Id # 25013-40 for Atlantic Aviation Serv. Inc. Phila. Pa. New E.H.-3273 lbs New E.H.C.H.- 77.7 in aft of datum. New Useful load- 1607 lbs. anti ice kit 55-3-1 Ser # 115

REMARKS	
MAINTENANCE -- REPAIRS -- ALTERATIONS	
RT	Installed new door lock & cam.
s been	new type exhaust stacks, new
ur or	pilot heater element, new brake
in an	linings on both sides, new type
	brake clips, new gyro filters,
	new rt. inst. panel, shock mt.
s	serviced shimmy dampener,
ation	installed new nose gear, tow bar
	two maintenance done see A.A.
	The above work was done at the
	-3-63 C/W Service Letter # 11.

REMARKS	
DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
7-11-63	Remov'd both propellers and installed 2 overhauled by Mc Cawley. Rt. Ser # 61592 Left. ser. # 61843. L. Maizenhalter Id # 25013-4 for Atlantic Aviation Serv. Inc. Phila. Pa.
7-29-63	Replaced both rt. + left brake linings L. Maizenhalter Id # 25013-40 for Atlantic Aviation Serv. Inc. Phila. Pa.

RE	LICENSE NUMBER	DATE	REMARKS
			INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
			TACH 444. 9-6-63
			Replaced brake lining both wheels, installed new O-rings in left wheel cyl. Installed new nose wheel tire.
			Seni J. Smith
			A# 1439661

TURE	LICENSE NUMBER	DATE	REMARKS
			ION — MAINTENANCE — REPAIRS — ALTERATIONS
			62-8-3 AD
			11-6-63 DARR
			490.20 Time
			E. Inc. AIRPORT has been inspected in accordance with a 400 Hour or Periodic inspection and determined to be in an airworthy condition. Date 11-6-63 Signature H. Mainmatter 26013-40 I.A., A&E, Repair Station Total Airframe or Engine Time 490:20
			Replaced main tires, both brake discs & linings, replaced top rotating beacon bulb flap up lite & clock lite pilots & co. pilots instruments filters, replaced both gear wheel halves with serviceable ones & installed anti-rattle clips as per Goodyear Service Bulletin AP-15. Replaced nose cone & cap. CW Service Bulletin 12, 10. AD-62-8-3. Removed dual control wheel & installed ram's horn wheel. New P.H. 3270, New EWC 575. New Useful load 1610 lbs. For private use, profit done. See A.B. work order # C7610. 5-7-73

JRE	LICENSE NUMBER	DATE	REMARKS
			CTION — MAINTENANCE — REPAIRS — ALTERATIONS
✓			Dec 18 1963 6 lbs meter installed at 509.40 hrs - meter reads 0000.00 Frank W. Shone ABE 1160878
✓			
✓			
✓			

JRE	LICENSE NUMBER	DATE	REMARKS
			INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		3-21-64	Tach Recording 46.0 hrs. Installed Nose gear Activator Rod # 35- 825185-19. Down Lock Riggings checked this date. Walt W. Jarrett A.G. 17603

TURE	LICENSE NUMBER	DATE	REMARKS
			INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		DATE 7-31 TACH TIME 94.0	I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 Hour INSPECTION AND WAS DETERMINED TO BE IN AN AIR-WORTHY CONDITION. MECH. Joe J. Reese NO. A-G 1081606

FLIGHT LOG

DATE	NATURE OF FLIGHT	No. of Pass.	TIME OF FLIGHT		TIME IN AIR		Miles Flown	REPAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.				
								I certify that this <u>AIRCRAFT</u> has been inspected in accordance with a <u>PERIODIC</u> inspection and was determined to be in airworthy condition. Details of inspection are on file at this agency under <u>TACH. 190.3</u> V.O. # <u>731</u> Date <u>12-24-64</u> Total Time <u>700.10</u> <u>John H. Crapo</u> AEP 1320759 AERO-SPEC., 240 Dale Ave. Fullerton, Calif. LA-16100 F.A.A. Repair Station #4451		
								I certify that this <u>AIRCRAFT</u> has been inspected in accordance with a <u>25 HR</u> inspection and was determined to be in airworthy condition. Details of inspection are on file at this agency under V.O. # <u>792</u> Date <u>4-2-65</u> Total Time <u>224.1</u> <u>John H. Crapo</u> AEP 1320759 AERO-SPEC., 240 Dale Ave. Fullerton, Calif. LA-16100 F.A.A. Repair Station #4451		
TOTALS FORWARD										
TOTALS TO DATE										

DA 2

REMARKS

RE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
Conformance airworthy 321.9 S		6-13-66	Notes 364.6 Indicator Turn & Bank replaced with overhauls H.B. 241.1 Serial NO. C 3156 Overhaul with serial tag dated 3-27-64 by Otto's Instrument Service Ontario International Airport Ontario Calif. Ed. Patrick B. Thompson A1454260

RE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
			7-8-66 Complied with Beech S. Letter - 12 (engine control modification). Repaired cabin door holds. Installed new battery. (418 hrs on meter). N. O. Hansen GOPHER AVIATION, INC. Rochester, Minn.

								Rochester, Minn.	

W.O.# 4849
AD NOTES
CHECKED THRU
67-5

Installed new brake housing and discs, seals and pucks, left hand side. Installed new seals and pucks R.H. side.

I certify that this AIRCRAFT has been inspected in accordance with § ANNUAL inspection and was determined to be in airworthy condition.
Aircraft total hrs. 1035
Engine total hrs. 1035 (LEFT) 487 (RIGHT)
Name Robert J. McLean
Rating C.R.P. 4020 Inspection
Date 3-2-67
MARTIN SCHOOL OF AVIATION, INC.
No. 4027

TOTALS FORWARD	
TOTALS TO DATE	

REMARKS

RE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		1-17-68	HOURLMETER 633.5 Complied with AD 67-29-1 by inspecting rudder spar. no cracks found. Martin Aviation, Inc. E. E. Jorgenson. A+P 1617068

FLIGHT LOG

DATE	NATURE OF FLIGHT	No. of Pass.	TIME OF FLIGHT		TIME IN AIR		Miles Flown	REPAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.				
I certify that this <u>Aircraft</u> has been inspected in accordance with a <u>Annual</u> inspection and was determined to be in airworthy condition.										
Aircraft total hrs. <u>1167</u> TACH. <u>1658</u> Engine total hrs. <u>LEFT 1167</u> <u>RIGHT 559</u> Name <u>Gordon E. Koch</u> Rating <u>AMP 1552617 Repair Station Insp.</u> Date <u>3-22-68</u>										
MARTIN SCHOOL OF AVIATION, INC. No. 4027										

REMARKS

[illegible]

FLIGHT LOG

DATE	NATURE OF FLIGHT	No. of Pass.	TIME OF FLIGHT		TIME IN AIR		Miles Flown	REPAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.				
8/29/68	Log meter	6861								
	Replaced The left hand engine compartment cowling flap actuator. Replaced and Balanced Both main gear tires. aired all three gear struts, straightened dent in R/H outboard gear door.									
	NORMAN LARSON CO. 1240 Hayvenhurst Ave., Van Nuys, Calif. REPAIR STATION 4095									
	A.H. Jensen 8-29-68									

E LICENSE
NUMBER

DATE

INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS

9-10-68 Hobbs Time: 715.2
 Accomplished eng. oil chg; pulled filters,
 + ran for 1h. check. O.I. Texaco 50.

Woods #1576011

6/8/69 TACH. TIME 836.3

I CERTIFY THAT THIS AIRCRAFT HAS
 BEEN INSPECTED IN ACCORDANCE WITH
 A FAA INSPECTION AND
 WAS DETERMINED TO BE IN AN AIR-
 WORTHY CONDITION.

MECH

NO

John Beese
1A-0081608

Two Aust Corp
 Fullerton Airport
 RO-3628
 Eng S/N-C3-91949-52
 and S/N C3-91965-52+

were not in the aircraft
 Jan 10. 1969 By Pauli Corp.

NUMBER

1976

AP 181908Z

22

Date June 2, 70 Total Time 1523 Hr. Mete. 1014.

I certify that this aircraft has been

Inspected in accordance with a 24 NOV 71
inspection and was determined to be in
airworthy condition.

airworthy condition.

TOTALS FORWARDS

Inspection Authorization

"CLIFF" FRAIZER'S

A & E INSPECTION SERVICE
Orange County Airport

FLIGHT LOG

DATE 1972	NATURE OF FLIGHT	No. of Pass.	TIME OF FLIGHT		TIME IN AIR		Miles Flown	REPAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.				
Feb 6		Hobbs			1326.8			25 hr check add bat. water- hyd. fluid ok, inflate tires install new bearing cone in nose wheel. <i>Bliff Franjer</i> At 12402		
AD 67-29-1								AD's 67-29-1 spr wed		
AD 68-26-6								68-26-6 placards		
AD 72-1-2								72-1-2 Oil drain hoses.		
AD 72-11-2								72-11-2 Fuel disruption & placards.		
AD 72-17-2								72-17-2 Zerk in up lock roller above c/w <i>Bliff Franjer</i>		

Feb 6 1972
1326.8

REMARKS

RE	LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS
		1972	
Master records 1 2			Sept. 1 installed alt. meter overhauled by Aero Inst. and checked static system in accordance with FAR 91.170 All new tires installed, wheels & bearings checked & lubed, cycled & lubed landing gear.
			Date <u>Sept. 1, 72</u> Total Time <u>1923</u> I certify that this <u>aircraft</u> has been inspected in accordance with a <u>annual</u> inspection and was determined to be in airworthy condition. <u>Cliff Fraizer</u> AWP 12407 Inspection Authorization "CLIFF" FRAIZER'S A & E INSPECTION SERVICE Orange County Airport Santa Ana, California
records 20 pages			

FLIGHT LOG

DATE	NATURE OF FLIGHT	No. of Pass.	TIME OF FLIGHT		TIME IN AIR		Miles Flown	REPAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.				
I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. DETAILS OF THIS INSPECTION ARE ON FILE AT THIS AGENCY UNDER W/O # <u>5450</u> SIG. <u>[Signature]</u> DATE <u>10-23-73</u> <u>1618.8</u> <u>TOTAL TIME</u> <u>2122.4</u> APPROVED REPAIR STATION #4874 MISSION BEECHCRAFT 18741 NORTH AIRPORT WAY ORANGE COUNTY AIRPORT SANTA ANA, CALIFORNIA 92707 REPLACED LEFT BRAKE LININGS AND BACKING PLATE, INSTALLED LEFT MAIN GEAR RETRACT ROD AND RIGGED, REPLACED BOTH RETRACT ROD BOOTS ON MAIN GEAR A.D. 67-29-1 RUDDER SPAR INSPECTED - NO CRACKS FOUND. A.D. 72-22-1 INSPECTED ROLLERS AS PER PARAGRAPH (A) FOUND TO BE OK FOR SERVICE. ZERIL FITTING BOLTS PREVIOUSLY INSTALLED ON A.D. 72-17-2. FOUND CONTROL WHEEL CRACKED UPON INSPECTION AS PER A.D. 62-8-3. REPLACED WITH NEW CONTROL WHEEL P/N 60-524080-13 AND ADAPTER										
TOTALS FORWARD								(CONT'D) (NEXT PAGE)		
TOTALS TO DATE										

REMARKS

LICENSE NUMBER	DATE	INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS

REMARKS

LICENSE
NUMBER

DATE

INSPECTION — MAINTENANCE — REPAIRS — ALTERATIONS

(CONT'D)

PH 96-524029-31. INSTALLED RIGHT AUX FUEL
CELL AFTER REPAIRS BY A.R-TECH SERVICES.
REPLACED LEFT MAIN FUEL DRAIN VALVE. ADJUSTED
LANDING GEAR UP & DOWN LIMIT SWITCHES FOR
PROPER GEAR BOX TRAVEL AS PER BEECH MODEL 55
SERVICE MANUAL.

SERVICEABLE

MEGR. NAME: *W. J. Fitch*
COMPONENT NAME: *Fuel Cell*
PART NO.: *95-920011-6*
SERIAL: *M-279*

The aircraft component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency and is approved for return to service.
Pertinent details of the repair are file at this repair station under
WORK ORDER NO. *1072*
DATE: *10-13-73*
SIGNED: *[Signature]*

AIR-TECH SERVICES
8147 Secura Way
Santa Fe Springs, California
F.A.A. Certified Repair
Station No. 4758

DG

DATE	NATURE OF FLIGHT	No. of Pass.	FLIGHT				PAIRS — ADJUSTMENTS — REMARKS	SIGNATURE	LICENSE NUMBER
			Up	Down	Hours	Min.			
7-3-74	INSTALLED NEW NOSE GEAR RETRACT ROD IN COMPLIANCE WITH BEECH SKI 0600-205. LUBED LANDING GEAR						MISSION BEECHCRAFT 18741 NORTH AIRPORT WAY ORANGE COUNTY AIRPORT SANTA ANA, CALIF. 92707 ARS 4874 W.O. 6358 TIME 1726 SIG. <i>[Signature]</i> INSP.		
JUL 18 1974	Minor Alteration. Removed TURN & BANK indicator & Directional Gyro. Installed EDO-Aire Mitchell Cent I Auto-Pilot w/ WDR TRACKER. Installed 3" Directional Gyro Auto-Pilot installed per STC SA 1300SW & kit # AK-330						The alteration described above was performed in accordance with Standard Airworthiness Practices & FAA AC 43.13-1, 2. See A/C Flight Manual for revised weight and balance.	<i>[Signature]</i>	
TOTALS FORWARD									

For Airadio Co., Inc. FAA Repair Station 4478
Orange County Airport - Santa Ana, Calif.

RADIO INSPECTION AND REPAIR

FREQUENCY CHECKED			REPAIRS		
DATE	INSPECTED BY	RESULTS	DATE	REPAIRED BY	REPAIRS MADE
1/31/77		RESRALED NOSE STRUT & SHIMMY DAMPER, INSTALLED NEW NOSE TIRE.			<i>Paul W. Luthy</i> W/O 1081 TIME 2083.1 LONG BEACH EXECUTIVE AIR TERMINAL ARS 405-47
8-3-77		REMOVED COLLINS NAV SYSTEM, NARCO GHDG SLOPE & GYRO INSTALLED KING KX170A-K1211B & K11A20 AUDIO PANEL			<i>DeLander</i> RR 1482657
			PABAS AIRCRAFT RADIO EAA STATION NO. 4035 PALOMAR AIRPORT CARLSBAD, CALIFORNIA		

RADIO INSPECTION AND REPAIR

FREQUENCY CHECKED			REPAIRS		
DATE	INSPECTED BY	RESULTS	DATE	REPAIRED BY	REPAIRS MADE
8-5-77		Swung magnetic compass, installed compass correction card. Adjusted right vacuum regulator.			<i>Paul H. Brunkman</i> 947#560807528
8-5-77		CHECKED TRANSPONDER PER PART 43 APP. F.			<i>DeLander</i> RR 1482657

MEMORANDUM

DATE _____

Service Bulletins C/W

- #11- Rudder replacement - 8-10-61
- 2- Cabin light circuit breaker - 5-11-62
- 8- Rudder balance wt. screws - 5-11-62
- 7- Eng. Mt. bolts 3-2-62
- 10- Eng. Mt. drain holes - 6-15-62
- 9- Engine horn control wheel - 10-9-62
- 12- Fuel vents + strainer fittings - 10-9-62, 11-6-63
- 14- Landing gear uplocks rollers - 11-6-63

MEMORANDUM

DATE _____

Service Letters C/W

- #4 Fuel quantity circuit 10-9-62
- #5 Winterization kit - 3-2-62
- #11- Increased baggage - 5-3-63

2

AIRCRAFT LOG BOOK

CATALOG #LO-5

© 1965 JEPPESEN & CO. DENVER, COLORADO

.250

THICKNESS

GREEN

GRAY

CLEAR

TOTAL TIME = HOBBS + 509.4

AIRCRAFT LOG FOR

BOOK NO. 2

MAKE Beech

MODEL 95-55

SERIAL NO. TC-157

REGISTRATION NO. N 1357 Z

DATE MFG. 7-5-61

MAKE OF ENGINE

MODEL

SERIAL NO.

PROPELLER PWC-C34F-2F RT. S/N EBS45 LT. S/N EBS44

APPROVED FWD CC UNIT

field cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
1970	July 13-70 tach time 1033.8 Hrs total time 1542.8 Hrs Installed Beech Brake Kit 55-8002-1P S/N 142 Changed nose tire & Modified wheel for tube. Changed L.H. upper Lip on Cowling MISSION BEECHCRAFT 18741 NORTH AIRPORT WAY CRS 4874 ORANGE COUNTY AIRPORT W/O 1893 SANTA ANA. CALIF. 92707 CMazzard insp.
Aug 11	check bot. water, brake fluid & Tires to 50 psi. Shiff Frasier

field cell

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

DATE

Feb 4 1971 25 hr Inspection Change oil 11 qt Each Engine
cleaned screens Cleaned plugs Check battery water
aired tires 50 PSI

DATE 1971	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
Aug. 6	Hr Meter	1258:2	:			
Sept. 24	Hr Meter	12-82:9	:			
May 17-19 74	25 hr	25 hr	:			
Robb's Meter	1691:7		:			
:	:	:	:			
:	:	:	:			

Chambers Brake rotor & Drum
J. B. Van Der

Aug 6	25 hr. check	check bot. hyd fluid & air in tires,	bluff Fraizer ATP 12482
Sept. 24	25 hr. check,	check bot. water/hyd. fluid & air in tires,	bluff Fraizer ATP 12402

fuel cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
1974	Jack A/C & cycle gear, all wheels removed
Dec. 8	bearings cleaned, inspected & repacked, 1 new bearing cup in nose wheel.
	both O-rings replaced in right brake.

Date Dec. 8. 74 Total Time 2297

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
2-20-75						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
:						
TOTALS	:	:	:			

INSTALLED NEW ELEVATOR TRIM TABS
AND ACTUATOR RODS IN COMPLIANCE WITH
S/I 0610-152 PARTS I, II AND III.

AD 75-16-10 CW

MISSION BEECHCRAFT
18741 NORTH AIRPORT WAY
ORANGE COUNTY AIRPORT
SANTA ANA, CALIF. 92707
ARS 4874

W. O. 1256
TIME 1259.2
SIG. [Signature] INSP.

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

75-16-10
01-16-10

fuel cell

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

APR 30 1975

MAJOR Alteration - Installed TRANS-CAI Industries Remote Encoder Model D120-P2-T Serial No. 22227 & matched with existing Pilot's Altimeter S/N 5027. Correspondence check Required by FAR 91.36 Accomplished in Accordance with AC 43.6. Static System Leak check Accomplished in Accordance with FAR 43, Appendix E, Part (A). SEE FAA FORM 337 This Date.

The alteration described above was performed in accordance with Standard Airworthiness Practices & FAA AC 43.13 - 1, 2. See A/C Flight Manual for revised weight and balance

For Alradio Co., Inc. FAA Repair Station 4478 Orange County Airport - Santa Ana, Calif.

DATE

GROUND TIME

AIR TIME

TOTAL TIME

SIGNATURE OF PERSON MAKING ENTRY

TACHOMETER READING

INSPECTION REFERENCE DATA

BRT. FWD.

7-21

1 HOUR METER

1871.8

CENTURY I PANEL UNIT. CHANGED OUT THIS DATE S/N 5030

Date 7-21-75 Repair Order No. 725 Tack Time 1871.8
I certify the above mentioned repair(s) are airworthy.
Signed [Signature] for

Edo-Aire Mitchell
1601 Skyway Dr.
Bakersfield, CA 93308
Repair Station No. 242-2, Limited Rating

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

7-22-75

Installed Pointer model 3000 ELT system This Date
New A/C empty wt 3279.15 LBS New CWCS 77.88'

The alteration described above was performed in accordance with Standard Airworthiness Practices & FAA AC 43.13 - 1, 2. See A/C Flight Manual for revised weight and balance

For Alradio Co., Inc. FAA Repair Station 4478 Orange County Airport - Santa Ana, Calif.

BRT. FWD.	TIME	TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	
11-4-75				INSTALLED NEW HARTZELL THREE BLADED PROPELLERS MODEL PHC-C34F-2F WITH: BLADE MODEL NUMBER FC7663-2R. S/N: EBS44 INSTALLED ON LEFT ENGINE AND S/N EBS45 ON RIGHT ENGINE, PROPS INSTALLED WITH C3567-1P SPINNER ASSEMBLYS APPROVAL FOR INSTALLATION IS AIRCRAFT SPEC 3A16 ITEM 9(b). SEE AIRCRAFT FLIGHT MANUAL FOR REVISED WEIGHT AND BALANCE. ALSO SEE: FAA APPROVED MANUAL 115F DATED MARCH, 1975			MISSION BEECHCRAFT 18741 NORTH AIRPORT WAY ORANGE COUNTY AIRPORT SANTA ANA, CALIF. 92707 ARS 4874
TOTALS				W. O. ... 8101 TIME 1951 All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.			

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

12-19-75 INSTALLED EXTENDED NOSE CONE
AS PER INSTALLATION DRAWINGS FOR
BERCH KIT 55-4007M. ALSO INSTALLED
NOSE GEAR MOUNTED TAXI LIGHT.
SEE AIRCRAFT FLIGHT MANUAL FOR
REVISED WEIGHT AND BALANCE.

MISSION BEECHCRAFT
18741 NORTH AIRPORT WAY
ORANGE COUNTY AIRPORT
SANTA ANA, CALIF. 92707
ARS 4874

W. O. ... 8225

TIME 1942

SIG [Signature] INSP.

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

Jack A/C & cycle landing gear.
Wheels removed, bearings, cleaned, inspected &
repacked.
New bearing cups installed in nose wheel.
AD55-3-2 C/W & OK by inspect.
AD73-7-4 C/W lost annual by OH.

Date May 1, 1976

Total Time 2475

I certify that this aircraft has been

inspected in accordance with a 2977021
inspection and was determined to be in
airworthy condition.

[Signature] AIP 12402
VIA.

112304 UG/A

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
7-28-76						
INSTALLED OVERHAULED LEFT MAIN FUEL CELL: S/N 73-9662 THIS DATE. MADE AND INSTALLED NEW FUEL HOSE BETWEEN FUEL PUMP AND METERING VALVE.						
				MISSION BEECHCRAFT		
				18741 NORTH AIRPORT WAY		
				ORANGE COUNTY AIRPORT		
				SANTA ANA, CALIF. 92707		
				ARS 4874		
				W.O. 8934		
				TIME 5016.71		
				SIG. [Signature]		

2-20-75

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
	REMOVED OTTO EGT SYSTEM AND INSTALLED RADAIR E.G.T. SYSTEM. NO CHANGE IN WEIGHT AND BALANCE. REPLACE LEFT ENGINE THROTTLE AND MIXTURE CONTROLS. INSTALLED OVERHAULED VACUUM PUMP ON LEFT ENGINE. INSTALLED NEW BEULCRANK ON AILERON TRIM TAB. INSTALLED NEW SEALS IN PILOTS & CO-PILOTS LEFT MASTER CYLINDERS. REPLACED E.L.T. BATTERY FUNCTIONAL TEST OK. NEW BATTERY DUE FOR REPLACEMENT ON OR BEFORE MAY 1982. NO A.D. NOTE APPLICABLE AT THIS TIME.
	Date: 5-26-77 Tach: 2131.0 I certify that this aircraft has been inspected in accordance with a <u>Annual</u> inspection and was determined to be in airworthy condition. Details of this inspection are on file under work order # <u>1237</u> Long Beach Executive Air Terminal, Inc. Repair Station # 405-47 Airframe Class I & III Signed: [Signature]

BRT. FWD.	DESCRIPTION
Sept 30, 1977	ALTImeter Certified This Date. ENCODER Correspondence check Required by FAR 91.36 Accomplished in accordance with AC 43.6 & TESTED TO 20,000 ft. ATC TRANSPONDER System Tested for Compliance with FAR 91.177 & FAR 43, Appendix F
	YONG SOK FAA ARS AIRADIO CO., INC. # 4428 18741 No. Airport Way Orange County Airport Santa Ana, Ca. 92707

fuel cell

78

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

INSTALLED NEW RIGHT MAIN FUEL CELL (UNIROYAL S/N W3274) A.D. 78-05-06 NOT APPLICABLE TO THIS CELL OR LEFT MAIN AND RIGHT AUX BECAUSE OF MANUFACTURER OR CONSTRUCTION NUMBER, INSPECTED LEFT AUX PER A.D. 78-05-06 AND BRECH S/I 0895, FOUND OK FOR SERVICE. INSPECTED RUDDER SPAR PER A.D. 67-29-1 FOUND OK FOR SERVICE, LUBED UPLOCK ROLLERS PER A.D. 72-22-1 PART 'C'. INSTALLED NEW ONE PIECE WINDSHIELD PER STC 844WE INSTALLATION INSTRUCTIONS. REPLACED GENERATOR BRACKETS AND RUBBER PADS. E.L.T. OPERATION OK. CK'D IGNITION SWITCHER PER A.D. 76-17-15 OK FOR SERVICE.

Date: 5-15-78 Tach: 226018
I certify that this aircraft has been inspected in accordance with a ANNUAL inspection and was determined to be in airworthy condition. Details of this inspection are on file under work order # 2050

Long Beach Executive Air Terminal, Inc.
Repair Station # 405-47 Airframe Class I & III

Signed

[Signature]

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

8-15-78 Repaired Century I Aircraft, by repairing S2-V75-4 s/n 5053 Ground checked

Date: 8-15-78 Repair Order No. 4696 Tach Time 23320
I certify the above mentioned repair(s) are airworthy.
Signed *[Signature]* FOR
Edo-Aire Mitchell
1701 Skyway Dr.
Bakersfield, CA 93308
Repair Station No. 242-2A, Limited Rating

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

10-12-78 ALTIMETER & STATIC SYSTEM CHECKED PER FAR 91.170
ENCODER CHECKED PER FAR 91.136
AC 43.6A
TRANSPONDER CHECKED
PER FAR 91.170 PART 43 APP F

PAVED AIRCRAFT RADIC
CARLSBAD, CALIFORNIA

[Signature]
1482657

Cell

DATE	
12-5-7	

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:	I certify that this engine has been inspected in accordance with AD 72-12-06	AD 72-12-06	
Hub up lock rollers AD 72-12-06				has been inspected in accordance with AD 7603-06	AD 67-29-1	
Comp L six spr AD 7603-06				is determined to be in airworthy condition	AD 78-05-06	
19N Switch : N 7603-12				aircraft total time	AD 76-05-12	
rudder spar per AD 67-29-1				engine total time	AD 67-29-1	
part C : found OK				Memo	DATE 8-25-80	SR 1019
				Rating		
				Date		
8-25-80					Time 2531.5	

cell

2511.5

20

13

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft has been inspected in accordance with Annual inspection and was determined to be in airworthy condition

Aircraft total hrs. 1666 2531.5

Engine total hrs.

Name

Rating

Date

lub up lock rollers AD 72-12-06
 Insp L. Aux as per AD 78-05-06
 ign switch 76-05-12
 rudder spar 67-29-1

part C. found OK

c/w SB 1019 elevator push rods per Beach S/B instructions

THIS INSPECTION

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
1-13-81	:	:	:	REPLACED PARTS SHORTED MPIG POWER CONVERTER + ICS TRANSPONDER CHECK TRANSPONDER PER FAA 91.170 PART 43 APP F		
	:	:	:	PABAS AIRCRAFT RADIO FAA STATION NO. 8085 PALOMAR AIRPORT CARLSBAD, CALIFORNIA		

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	DATE
BRT. FWD.	:	:	:	I CERTIFY THAT THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY F.A.R. 91.170 HAVE BEEN PERFORMED. THE ALTIMETER HAS BEEN TESTED TO 20,000 FEET	Repaired Standby Compass AND Replaced gyro Filter		
	:	:	:	SIGNATURE <i>[Signature]</i>			
	:	:	:	DATE 6-1-81			
	:	:	:	FAA REPAIR STATION 405-4			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.			

cell

02 bottle Hydrostat OK.

LT removed for repair

DATE MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft

has been inspected in accordance with

Annual inspection and was

determined to be in airworthy condition

Aircraft total hrs. 2678 hrs. Habib

Engine total hrs. 1761086 IA

Name George Casado

Rating 6-1-81

Date 6-1-81

up lock rollers AD 72-12-06

INSB LT Aux as per AD 78-05-06

INSB IAN Switch AD 76-05-12

" Rudder Spar inspection AD 67-29-0

CW S/B 1019 elevator push rod

both replaced

repair Cowling RT engine

clean, pack wheel legs

clean all fuel strainers

replace all brake lining

Nothing follows

AD 72-12-06

AD 78-05-06

AD 76-05-12

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft

has been inspected in accordance with

Annual inspection and was

determined to be in airworthy condition

Aircraft total hrs. 2775

Engine total hrs. 1761086 IA

Name George Casado

Rating 6-15-83

Date 6-15-83

TRANSPONDER CHECKED

3-29-83

3-29-83

INSPECTOR

THE ALTIMETER AND STATIC SYSTEM
AUTOMATIC PRESSURE ALTITUDE REPORTING
SYSTEM TESTS REQUIRED BY FAR PART
91.171 HAVE BEEN PERFORMED. THE
ALTIMETER(S) HAVE BEEN TESTED TO

20,000 FT. ON (L) (R)

SIGNED George Casado DATE 3-29-83

AERO INSTRUMENT SERVICE

REPAIR STATION 405-4

DATE MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft

has been inspected in accordance with

Annual inspection and was

determined to be in airworthy condition

Aircraft total hrs. 2822.6

Engine total hrs. 1761086 IA

Name George Casado

Rating 8-10-83

Date 8-10-83

lub up lock rollers AD 72-12-06

*LT prop OH. 9-23-83

AERO INSTRUMENT SERVICE

JOHN WAYNE AIRPORT
19481 AIRPORT WAY SO.
SANTA ANA, CA 92707
(714) 756-8888

F.A.A. REPAIR STATION 405-4

MFG. Garmin

ITEM Altimeter

SERIAL NO. 5027

PART NO. 22-922-02

WORK ORDER NO. 21012

CUSTOMER NAME: Wm. Stone

INSTRUCTIONS: ☐ FUNCTIONAL TEST; ☐ RE CALIBRATE; ☒ STATIC TEST; ☒ CERTIFY;

☐ REPAIR; ☐ OVERHAUL.

PRELIMINARY INSPECTION: out of Cal. - rocky

HIDDEN DAMAGE INSPECTION: good

☒ DISASSEMBLED;
☒ REPLACED;
☒ REASSEMBLED;

WORK PERFORMED
☒ CLEANED; ☐ INSPECTED;
☒ REPAIRED DAMAGED PARTS
☒ CALIBRATED-SUB-ASSEMBLY

91.171 HAVE BEEN PERFORMED. THE
ALTIMETER(S) HAVE BEEN TESTED TO
20,000 FT. ON (L) Y (R)

SIGNED J. M. Varnum DATE _____
AERO INSTRUMENT SERVICE
FAA REPAIR STATION 405-4

MODEL 22-922-02 SERIAL NO. NARCO
SERIAL NO. REMOTE _____ HAS BEEN
TESTED PER FAR 91.172 DATE 8-30-85
AND HAS BEEN FOUND TO COMPLY
WITH FAR 43 APPENDIX "F" PARAGRAPH C
SIGNED J. M. Varnum
AERO INSTRUMENT SERVICE
FAA REPAIR STATION 405-4

IONS

and T.C.I. Blind
altimeter S/N 5027
Replaced

NARCO

1787
905
882

SECTION
REFERENCE
DATA

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft
has been inspected in accordance with
Annual inspection and was
determined to be in airworthy condition

Aircraft total hrs. 3019 Hobbs.

Engine total hrs.

Name George Casada

Rating 8-3-85

Date 1761086 1A.

W 17 → AT. mm 211

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT.	:	:	:	I certify that this <u>aircraft</u>		
FWD.	:	:	:	has been inspected in accordance with		
	:	:	:	<u>Annual</u> inspection and was		
	:	:	:	determined to be in airworthy condition		
	:	:	:	Aircraft total hrs. <u>3054 Hobbs.</u>		
	:	:	:	Engine total hrs.		
	:	:	:	Name <u>George Casada</u>		
	:	:	:	Rating <u>1761086 1A</u>		
	:	:	:	Date <u>3-4-87</u>		

INSPECTION
REFERENCE
DATA

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

I certify that this aircraft
has been inspected in accordance with
Annual inspection and was
determined to be in airworthy condition

Aircraft total hrs. 3094

Engine total hrs.

Name George Casada

Rating 1761086 1A

Date 3-15-88

LT prop OH Due

4 Hobbs.

AIR TIME		SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT.	PT. or time	certify that this aircraft has been inspected in accordance with <u>ANNUAL</u> inspection and was determined to be in airworthy condition Aircraft total hrs. <u>3139.6</u> Engine total hrs. _____ Name <u>John Gradall</u> Rating <u>IA 1505328</u> Date <u>6-1-89</u> Elt Mar 92		
FWD.	was repaired by			
	Aers Tech service			
	C.W. with S/B: 2942			
	replaced left fitting			
	with new fitting			
	PT# 95610005-3			
	PT fitting was aluminum			
	aluminum so no further			
	steps inspection required			
	3 Oxygen hydrostat			
	was done, OK for			
	5 gas			
TOTALS		All repairs, inspections, alterations must be endorsed by a certificated mechanic with name _____		

6-13-89 REMOVED COLLINS 615 FIA, 51 X3, 42281 & 42281. INSTALLED KING KX170B, K1209 & K123 & KA 39. SER ATTACHED 337

PABAS AIRCRAFT RADIO
FAA STATION NO. 4035
PALOMAR AIRPORT
CARLSBAD, CALIFORNIA

THE ALTIMETER, STATIC SYSTEM, AND AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM TESTS REQUIRED BY FAR 91.171 HAVE BEEN PERFORMED & FOUND TO COMPLY WITH FAR PART 43 APPENDIXES E. & F.
DATE 6-13-89 W.O.# 20628
SIGNATURE John Gradall
PABAS AIRCRAFT RADIO FAA #4035
PALOMAR AIRPORT, CARLSBAD, CA.

THE ATC TRANSPONDER TESTS AND INSPECTIONS REQUIRED BY FAR 91.177 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH FAR PART 43, APP F
MODEL # 1 AT50A SERIAL # 1 23427
2. _____ 2. _____
SIGNED John Gradall
W.O.# 20628 DATE 6-13-89
PABAS AIRCRAFT RADIO FAA #4035
PALOMAR AIRPORT, CARLSBAD, CA

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
9-19-90	C/W AD-No - 72-22-01 UP-LOCK ROLLERS LUBED <u>Manus Girlando 101601414</u>
9-18-90	C/W AD-No - 68-26-06-RY INSTALLATION OF PIKARD (TAKE OFF AND LANDING ON MAIN TAKES ONLY) <u>Manus Girlando 101601414</u>

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
5-28-91	:	:	3159:1			
Air CRAFT inspection: Panel. Removed and all Controls checked and locked. A/C Cable; Pulleys & Push Pull Tubes checked & lubed for back. Service inst #98-34774M-11. A/C Gear Retraction perform and Emergency Gear Extension checked. Transmission Fluid checked. Brakes checked & new lining installed on L side. Hyd Boost. Serviced. A/C Control. Lubed. Fuel Filters & screen checked & cleaned. A/C Ties changed & 1/2 inch jack all wheel bearings checked. A/C Light checked. Q.A. #3 90-01-14 checked by inspection. And no cracks found at this time. A/C 89-01-02 checked by inspection. Checked ok. A/C 72-22-01 checked up to 1000 lbs & checked ok by Insp.						
TOTALS	:	:	:	All repairs inspection		

DATE

A-1)

cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
A-1)	76-07-M check by Insp & check ok. A/C 88-21-02 checked Q.A. #1 73101-03. A/C Air Filters checked & changed. RSR L wing too NAT light. ELT POTTERING checked & EXP MARGAR. Repair Baffle on COTR Engines. two new brackets for Fuel Controller installed. all new synchropluss installed. BOTH prop. OIL by REN had and re installed back to A/C. Fuel Cap Fuel in. Tags were installed. and two Rocker Cover Gasket. Repair at Air Door on L engine. 3668
Date 5-28-91	Tach 3159:1 TT 3159 Hrs
I certify that this <u>Air CRAFT</u> has been found to be airworthy after execution of	
Annular. In accordance with FAA	
Regulations.	Signed: <u>[Signature]</u>

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	DATE
BRT. FWD.	:	:	:				
10-30-91	3201 10			INSTALLOR AIR SWITCH IN NOSE OF AIRCRAFT P/N 1498-2			
	:			SWITCH WIRED TO HOBBS METER.			
	:			Rebuilt JAYS AIRCRAFT PAINT, RS# JVYR016L W/O 4091			
	:						
	:						
	:						
	:						

cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
	AIRCRAFT RE-UPHOLSTERED AND INSPECTED. RETURNED TO
	SERVICE BY WORK ORDER #1756 FAA APPROVED REPAIR
	STATION # 412-50 16-27-91 CHIEF INSPECTOR
	<i>Daniel F. Wier</i> DANIEL F. WIER

S/N: TC 157		DATE: 5-28-91
MODEL: 95-55		S.Q. #: 3732
T. TIME: 3159.1		TOTAL TIME: 3889.1 3668 86
ENGINE LOG/AIRFRAME LOG		
2980 AIRWAY AVE., COSTA MESA, CA 92626 TEL: 714-433-2275 AND 714-433-2276		
FAA APPROVED REPAIR STATION # JVYR016L AEROSPATIALE AUTHORIZED REPAIR STATION		
THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR/REPLACEMENT ARE ON FILE AT THIS AGENCY.		
DATE: 5-28-91	SIGNED: <i>Samuel G. Hernandez</i> A & P: 8648566421A	
<i>Annual Insp</i> A1. 88-21-02 check by Insp A2. 90-08-14 check no OALC found at this time A3. 94-26-02 N/A by NOT 4/15/97		

N1357X

AERO INSTRUMENT SERVICE

Orange County Airport, 19481 Campus Drive
Santa Ana, California 92707
FAA Approved Repair Station No. 405-4

SERVICEABLE

MANUFACTURER <i>Garmin</i>	MODEL & TYPE <i>Altimeter</i>
SERIAL NO. <i>5027</i>	PART NO. <i>22-922-02</i>
REMARKS: <i>Certify Only</i>	WORK NO. ORDER <i>9429-1</i>
THE INSTRUMENT OR APPLIANCE DESCRIBED ABOVE HAS BEEN REPAIRED AND TESTED AND INSPECTED IN ACCORDANCE WITH CURRENT APPLICABLE REGULATIONS OF THE FEDERAL AVIATION AGENCY, AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE UNDER ABOVE WORK NO. ORDER.	
DATE <i>9-26-91</i>	SIGNATURE <i>[Signature]</i>

THE ALTIMETER AND STATIC SYSTEM AND AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM TESTS REQUIRED BY FAR PART 91.411 HAVE BEEN PERFORMED. THE ALTIMETER(S) HAVE BEEN TESTED TO *20,000* FT. ON (L) *✓*, (R) *---*
SIGNED *[Signature]* DATE *9-26-91*
AERO INSTRUMENT SERVICE
FAA REPAIR STATION DL3R453L "N1357X"

THIS TRANSPONDER MFG. *NARCO*
MODEL *AT50A* SERIAL NO. *---*
SERIAL NO. REMOTE *---* HAS BEEN
TESTED PER FAR 91.413 DATE *9-26-91*
AND HAS BEEN FOUND TO COMPLY WITH FAR 43 APPENDIX "F"
SIGNED *[Signature]*
AERO INSTRUMENT SERVICE
FAA REPAIR STATION DL3R453L "N1357X"



S/N: *TC157*
MODEL: *95-55*
T. TIME: *3236.6*

DATE: *1-7-92*
S.Q. #: *4138*
TOTAL TIME: *3766.0*

ENGINE LOG/AIRFRAME LOG

2980 AIRWAY AVE., COSTA MESA, CA 92626
TEL: 714-433-2275 AND 714-433-2276

FAA APPROVED REPAIR STATION # JVVRO16L
AEROSPATIALE AUTHORIZED REPAIR STATION

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR/REPLACEMENT ARE ON FILE AT THIS AGENCY.

DATE: *1-7-92* SIGNED: *562636676 John P. Shea*
A & P: *504956642M*

C/W ANNUAL INSPECTION AS PER JAYS ANNUAL INSP GUIDE
C/W AD 72-23-01 UPLOCK ROLLER NEXT DUE AT 3236.6 T
C/W AD 76-07-12 BENDIX IGNIT/SWITCH NEXT DUE AT 3256.6 T
C/W AD 91-17-01 PAINTED TRIM ACTUATORS
INSTALLED 4 FUEL DECALS BY FUEL FILLER CAPS.
REPLACED RT NAV, AND LANDING LIGHT BULBS.
REPLACED BOTH INDUCTION AIR FILTERS BA7605

ited

40685

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
5/11/92	—	3360:1	3869:5	AIRCRAFT INSPECTED IN ACCORDANCE WITH CURRENT MANUFACTURER'S AND FEDERAL AIR REGULATIONS. 100 HR INSPECTION COMPLETED. AIRCRAFT FOUND TO BE IN AN AIRWORTHY CONDITION AND APPROVED FOR RETURN TO SERVICE. DETAILS OF INSPECTION ON FILE WITH MECHANIC. : ELT BATTERY REPLACED, EXPIRES DEC '93. ^{EARY C. CRITCHFIELD} APR 13 1993		
11/1/92	REPLACED RIGHT MAIN TIRE AND TUBE, LEFT MAIN TIRE UTILIZED EXISTING TIRE. TIRES TUBES INSTALLED MERCURY 650 XB TYPE. ^{EARY C. CRITCHFIELD} APR 13 1993					
4/2/93	TAKE TIME 3462:6		TOTAL TIME	100 HR INSPECTION COMPLETED THIS DATE.		
ALL CONTROLS CHECKED FOR FULL TRAVEL, MOVEMENT, AND SECURITY AND LUBRICATED. REPLACED NOSE WHEEL TIRE W/ MERCURY 500 X 5. PAIR ENGINE ANTI ICE LINE UNCLAMPED. CW AD 7222-01 UPLOCK ROLLER DUE NEXT AT 3560.1. CW AD 7607-12 DUE NEXT AT 3560.1. CW AD 6729-01 RUDDER SPAR WEB DUE NEXT AT 3710.1. CW AD 9008-14 WING FORWARD SPAR CAPRI THROUGH RIGGING DUE NEXT AT 3660.1.						
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

Cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5/11/92	REMOVED PASSENGER STEP, REMOVED CORROSION, REINSTALLED. STEP DRILLED AND RIVETED PATCH ON TRAILING EDGE, RT. FLAP. RE-ATTACHED FUEL VENT LINE RT. WING. INSTALLED BEECHCRAFT STRUT OVERHAUL KIT, LEFT MAIN STRUT. SERVICED ALL LANDING GEAR STRUTS W/ NITROGEN. SERVICED PROPELLER AND ELT FOR PROPER OPERATION. SERVICED LANDING GEAR GEAR BOX W/ 9001 COMPLY WITH MANDATORY SERVICE BULLETIN FLAP ATTACH FITTINGS # ^{BECH} NO CORRECTIVE ACTION REQUIRED. FABRICATED NEW CO-PILOT'S LEFT BRAKE FLEX LINE ^{HYD. STATIC TEST AND 6114} NO OXYGEN SYSTEM FUNCTION CHECK. SERVICED BATTERIES + BLEED BRAKES. ELT BATTERY DUE DEC 1993. PERFORMED LANDING GEAR RETRACTION TEST, NO BINDING OR DEFECTS NOTED. EMERGENCY GEAR EXTENSION COMPLETED. UPLOCK ROLLERS LUBRICATED. AIRCRAFT APPROVED FOR RETURN TO SERVICE. ^{EARY C. CRITCHFIELD} APR 13 1993 AT P 53482831K
	END
	NOT USED

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
04-02-93-	3462.6	11	:	I certify this Aircraft has been		
				inspected with an Beechcraft 95-55 Annual Inspection Check Sheet		
				and found to be Airworthy. AD 72-22-01 C/w next due 3560.0. AD 76-07-12		
				C/w due next 3460.1. AD 67-29-01 C/w due @ 3710.1. AD 90-08-14 C/w		
				due next 3660.01. End- Refanlujane B37404919 AI		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5-7-93	Remount H209, OG and installed WSO-360A-15, HAN22 KAN88 + WX900
MAINTENANCE RELEASE	
The component identified was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of the repairs are on file at this Repair Station under work order <u>10099</u> date <u>5-7-93</u>	
Signature <u>[Signature]</u>	Type of Certificate/Number <u>23X303A15</u>
for CRS BDKR393C, STC Aviation, Inc., St. Cloud, MN 56302.	

CALIBR.

UNREK

2-20-75

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
June 11, 1993				Hobbs 3527		
:				Installed overhauled Edo-Aire 5000F attitude gyro sh A234745.		
:				See yellow tag 3-4-50.		
:					BUFFALO AVIATION	
:					RT. 5, BOX 128	
:					BUFFALO, MN 55313	
:					612-682-5452 - 473-3644	
:					Work Order # 2628	
:						
:						
July 6, 1993				Hobbs 3557		
:				Replaced left tire with 6.50 x 8-8 ply Axt Hawk. Replaced left		
:				wheel brake linings. Cleaned & repacked wheel bearings		
:				Travis Brown ACP1782142		
:				Work Order # 2630		
TOTALS	:	:	:			
All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.						

Cell

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
July 9, 1993	Hobbs 3563
	Replaced right tire with 6.50 x 8 8 ply Axt Hawk. Replaced right brake disc p/n 141-27 & brake linings p/n 6644. Cleaned & repacked wheel bearings. Replaced one bearing race. Complied with AD72-22-01 by greasing up lock rollers - next due at Hobbs 3663. Complied with AD76-07-12 by "off" checking both ignition switches - ok - next due at Hobbs 3663.
	Travis Brown
	ACP1782142
	BUFFALO AVIATION
	RT. 5, BOX 128
	BUFFALO, MN 55313
	612-682-5452 - 473-3644
	Work Order 2633

40685

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE
07-10-1996 N1357Z Hobbs 3644.4 TT 4153.8	Lt. prop SOH 821.8 Rt. prop SOH 485.9					
Aircraft lubed and inspected in accordance with BEECHCRAFT Service Manual.						
1. Lubricated prop and mixture control cables.						
2. Replaced batteries.						
3. CW AD 91-17-01, amdt 39-7099, 11-25-91, Inspected and color coded elevator trim tab actuators in accordance with Beech SB # 2399.						
4. CW AD 82-07-03, amdt 39-4354, 5-6-82. Performed decay test on heater IAW Janitrol Instruction Instruction 24E25-1.						
5. CW AD 72-22-01, amdt 39-1544, 10-25-72. Lubricated the uplock mechanism in accordance with Beech Service Instruction No. 0448-211. (Due again at Hobbs 3744.4)						
6. Replaced both uplock springs and replaced left downlock spring, inspected down lock springs for proper tension.						
7. Replaced both seals and lower bearing in Landing Gear Actuator Assembly.						
8. CW AD 90-08-14 amdt 39-6563, 5-7-90. Examined wing forward spar carry-through web structure for cracks.						
9. AD 89-05-02, amdt 39-6144, 3-24-89, N.A., SEE LOG ENTRY DATED 6-1-89						
10. CW AD 91-17-01, amdt 39-7099, 11-25-91, Painted stab rear spar, inspection hole ledges & actuators IAW SB 2399.						
11. Lubricated all landing gear grease fittings.						
12. Lubricated all control cable pulleys and checked control cables.						
13. Cleaned and greased wheel bearings.						
14. Rebuilt both rt. master cyls.						
15. Rebuilt and bled both wheel cyls.						
16. Landing gear retract check normal.						
ELT due 10-96						
Ran up. All instruments within normal parameters and mag switch operational checks normal.						
I certify this AIRCRAFT has been inspected in accordance with an ANNUAL INSPECTION under current F.A.A. regulations, and has been found to be in an airworthy condition and has been released for service this date.						
<i>Richard Phillips</i> Richard Phillips IA476340258						
TOTALS						

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

07-10-
N1357
Hobbs

Aircraft
Manual

1. CW, (Due
2. CW, accoi
3. CW A mect No. 0.
4. CW Al carry-
5. Rebuilt
6. Cleaned
7. Landin
8. Inspect
- ELT due 1
- Ran up, operationa

I certify
ANNUAL IN
found to be
this date.

Richard Phillips
Richard Phillips

07-10-1996
N1357Z

Hobbs 3646.4 TT 4155.8 Lt. prop SOH 823.8
Rt. prop SOH 487.9

Aircraft lubed and inspected in accordance with BEECHCRAFT Service Manual.

1. CW AD 67-29-01, amdt 39-574, 10-27-87, Inspected rudder spar web. (Due again at 3896.4)
2. CW AD 94-17-13, amdt 39-8704, 9-15-94, Inspected both prop hubs in accordance with SB #165 (Due again at 3896.4)
3. CW AD 72-22-01, amdt 39-1544, 10-25-72. Lubricated the uplock mechanism in accordance with Beech Service Instruction No. 0448-211. (Due again at Hobbs 3746.4)
4. CW AD 90-08-14, amdt 39-6563, 5-7-90, Examined wing forward spar carry-through web structure for cracks.
5. Rebuilt nose strut.
6. Cleaned, inspected and repacked wheel bearings.
7. Landing gear retract check normal.
8. Inspected ELT battery and ELT for condition and proper operation.

ELT due 10-96
Ran up. All instruments within normal parameters and mag switch operational checks normal.

I certify this AIRCRAFT has been inspected in accordance with an ANNUAL INSPECTION under current F.A.A. regulations, and has been found to be in an airworthy condition and has been released for service this date.

Richard Phillips
Richard Phillips IA476340258

07/24/1996
N1357Z
Hobbs 3650.1

1. Replaced right door window, see form 337.
2. Replaced both batteries.

Richard Phillips
Richard Phillips AP476340258

LIBRARY

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	09/05/96	Hobbs	3672 HRS	C/W A.D. 67-29-01 By	Installing doublers / c/p	
:	:	:	:	as required P/Ns 96-630000-305, -309, -311 resp.		
:	:	:	:	No further action required. Resealed L.H. wheel cylinder		
:	:	:	:	& bleed, relined with new pads.		
:	:	:	:			

[Signature]
AP 558808083

I certify that the static system, altimeter, encoder, and transponder tests required by FAR Part 91.411 and 91.413 were performed I/A/W FAR Part 43, Appendices E and F as applicable. Tested to 20,000 feet. Details of this inspection are on file under Work Order No. 6091001. Tach Certificate No. 2429052 FAA CRS IAZR154K.

[Signature] Inspector. Dated 7-10-96
Independence Aviation LTD. Orland Airport Phone 916-865-3677

cell

96

SECTION
REFERENCE
DATA

DATE

NCE, INSPECTIONS, REPAIRS AND ALTERATIONS

10/18/96 Hobbs 3696 HRS. Removed & replaced L.H. fuel cell (35-380135-9 s/n 899) see Yellow Tag Aero Tech W.O.# 8884, 10-17-96. L.H. Tach-Gen. replaced with Overhauled unit, see Yellow tag Weco W.O.# BW645-95, H60-050 s/n 51-01562. Resealed R.H. wheel cylinder & Bleed brake.

12/28/97 Hobbs 3715 HRS. Replaced L.H. Generator Switch with new (35-380052). Replaced fuel Drain seals (See Tags) c/w A.D. 96-20-07 Heater Press Decy test P/N 9. Heater Hobbs Meter installed at this time Meter Reading 685 HRS. Next due 02/99 or 1-Hobbs reading 785 HRS.

[Signature]
AP 558808083

[Signature]
AP 558808083

ificated

Fuel Cell

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	DATE
BRT. FWD.	08/09/97	Hobbs :	3765 Hrs	Lubed controls, pullers, rod ends, hinges		Serviced	08/97
	:	T.T. = :	4274 Hrs	battery, brakes, fuel gascolator, E.L.T. checked		I.A.W.	
L.H. prop.	T 504 = :	942 Hrs	FAR PT. 91.2070, battery next	due Aug. 99. Oxygen bottle removed			
R.H. Prop.	T 504 = :	606 Hrs	and Hydrostatic tested by Hughes	(7-11-97 L21041) Replaced door lock			
Heater Hobbs	:	686 Hrs	with new, Replaced Loren antenna	with servicable unit. Both air filter			
	:	:	:	elements replaced with new, Replaced E.L.T. indicator from OTOS.			
	:	:	:	C/W A.D. 72-22-01 Uplock roller lube, R.D.H. 3865, C/W A.D. 76-07-12			08/20/99
	:	:	:	By Switch grounding C/W A.D. 97-14-15 By latch operation O.K.			
	:	:	:	Ran up and all ops normal			
	:	:	:	CERTIFY THAT THIS Aircraft HAS BEEN			
	:	:	:	INSPECTED IN ACCORDANCE WITH AIR			
	:	:	:	INSPECTION AND WAS DETERMINED TO BE			
	:	:	:	AIRWORTHY CONDITION.			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.			

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

DATE	TIME	REMARKS
08/97	Hobbs Tach 3774 Hrs	Replaced elevator (L.H.) O+BP hinge pins as required, L.H. aileron bellcrank pins replaced due to wear. Replaced (L.H.) engine tach - Gen. cannon plug. RAR R.H. propeller for Reasil/Repair. A.P.S. W.O. no. 26514, 11/21/97.

08/20/99 Hobbs 3792.0 Total Time 4311.0
 ANNUAL INSPECTION PER INSPECTION CHECK LIST #0927.
 INSPECTED & LUBRICATED ALL PULLEYS, CABLES, BELL CRANKS
 ETC. THROUGHOUT CABIN, FUSELAGE, WINGS & EMPENNAGE.
 JACKED AIRCRAFT PERFORMED GEAR RETRACTION TEST
 AND ADJUSTED ALL LANDING GEAR DOORS, SERVICED STRUTS
 WITH 5606 HYDRAULIC FLUID & NITROGEN, CLEANED & REPACKED
 WHEEL BEARINGS, 'CONTINUED ON NEXT PAGE'

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	DATE
BRT.	:	:	:				10-20-98 T
FWD.	:	:	:				A
10-20-98	TACH	3792.0	:	CONTINUED: INSTALLED NEW LT MAIN			W
:	:	:	:	TIRE, REPLACED BRAKE LININGS AND			A
:	:	:	:	SERVICED BRAKES WITH 5606 HYDRAULIC			R
:	:	:	:	FLUID, SERVICED & CHARGED BATTERY			
:	:	:	:	INSPECTED & TESTED FLT PER FAR			
:	:	:	:	91.207 (D). COMPLIED WITH BEECHCRAFT			
:	:	:	:	SERVICE INSTRUCTION #1019 INSPECTION OF			
:	:	:	:	ELEVATOR CONTROL PUSH RODS, REVIEWED AND			
:	:	:	:	COMPLIED WITH ADS 67-29-01 - RUDDER SPAR			
:	:	:	:	WEB INSPECTION, 72-22-01 - LG GEAR UP-LOCK			
:	:	:	:	ROLLERS, 82-07-03 JAWITROL HEATERS DUE AT			
:	:	:	:	785 HEATER HOBBS TIME. "CONT. NEXT PAGE"			

INSPECTION REFERENCE DATA	DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
LT MAIN INGS AND HYDRAULIC BATTERY ER FAR BEECHCRAFT CTION OF iewed AND den SPAR re up-lock s Due at xt PAGE"	10-20-98	TACH 3792.0 CONTINUED: Ad 89-05-02 NO longer APPLIES DUE TO NEWER ALUMINUM FITTINGS, 90-08-14 Comp with Dy Dye Penetrant INSPECTION. & Ad. 97-14-15 CW Per Ad NOT REQUIRED. THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE Kenneth J Clark AIP 263178947
	DATE 10-20-98	TACH 4311.0
		TOTAL AIRCRAFT TIME 3792.0
		I CERTIFY THAT THIS AIRCRAFT HAS BEEN
		INSPECTED IN ACCORDANCE WITH AD 263178947
		INSPECTION AND WAS DETERMINED TO BE IN
		AIRWORTH CONDITION.
		SIGNATURE: Kenneth J Clark
		A&P # 263178947 FA

Structural

Repair

See Hobbs
12-18-63

Specialists



(952) 447-7737

DATE

A/C TT: 4311.4 DATE 10 April 01

INSPECTED AIRFRAME I/A/W BEECH BARRON SERVICE MANUAL 100 HOUR
INSPECTION LIST AND FAR 43 APP D. JACKED AIRCRAFT PERFORMED
GEAR SWING CHECKED EMERGENCY EXTENSION, CLEANED AND PACKED
WHEEL BEARINGS, CHECKED LANDING GEAR BOX OIL LEVEL ADDED 2 OZ.
MOBILE 636, CLEANED AND INSPECTED FUEL SCREENS, LUBED ALL
CONTROL PULLEYS AND CONTROL CRANKS, CHECKED STALL WARNING,
SERVICED BATTERY, ELT OPVS CHECK OK, BATTERY CHANGE DUE
OCTOBER 01, COMPLIED WITH THE FOLLOWING RE-OCCURRING ADS
72-22-01 UPLOCK ROLLERS BY LUBRICATION
90-08-14 SPAR INSPECTION COMPLIED WITH LAST ANNUAL
96-20-07 JANITROL HEATER C/W LAST ANNUAL
97-14-15 CABIN SIDE DOOR, CHECK OK

I CERTIFY THIS AIRFRAME HAS BEEN INSPECTED I/A/W AN ANNUAL
INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION,
THE FOLLOWING ITEMS NEED COMPLIANCE: PITOT STATIC INSPECTION

A&P 385842869 I/A

Paul Shaw

ated

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA	DATE
------	-------------	----------	------------	----------------------------------	--------------------	---------------------------	------

November 1, 1999

N1357Z

Hobbs 3799.9

N1357Z CONT. 11/01/99 Hobbs 3799.9

Total Time 4318.9

Annual Inspection per inspection check list #0927. Inspected and lubricated all cables, turn buckles, bellcranks etc. through out the fuselage, cabin, wings and empennage. Jacked aircraft and repacked main wheel bearings and installed new bearings and races in the nose wheel. Serviced all tire pressures with compressed air and serviced all landing gear struts with 5606 and nitrogen. Performed gear retraction and emergency extension test, lubricated all struts, and up-lock rollers, serviced brakes with 5606 hydraulic fluid, removed battery serviced, charged and cleaned battery box, inspected and all fuel cells and fittings, installed new ELT battery and tested per FAR 91.207 (D) new battery due date Oct. 2001. Replaced RT. Lower nav. bulb. Reviewed AD's Complied with AD's 67-29-01 spar web, 72-22-01 up-lock rollers, 96-20-07 Janitrol heaters, 89-05-02 elevator control fittings, 90-08-14 wing spar structure, 97-18-02 door handle lock, Test ran aircraft.

This Aircraft is approved for return to service.

Kenneth J Clarke

Kenneth J Clarke

&P 263178947 IA

11/01/99 TO 4318.9
THAT THIS Aircraft HAS BEEN
INSPECTED IN ACCORDANCE WITH AN ANNUAL
INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY
CONDITION AND IS APPROVED FOR RETURN TO SERVICE

SIGNATURE: *Kenneth J Clarke*

I & P 263178947 IA

TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or an agency with name, rating and cert. no.
--------	---	---	---	--

DATE

BRT.
FWD.

Date:5-23-2002

Beachcraft MOD:95-55 S/N:TC-157 REG:N1357Z
Removed: King KMA-20, KX-170B, KX170B, KI-211C, KI-208, KA-39,
II Morrow 612B, A-15, Narco AT-50A, Motorola 5614C, 4056A, 5534A,
Sigtronics SPA400

Details on file at this repair station on INV. 5227 Dated 5/23/02.

Avionics Masters Inc.
5915 NW. 24th Way
Ft. Lauderdale, FL. 33309
FAA CRS VIMRO95K


KEN BORZAGE
2400994

XXXXXXXXXXXXXXXXXXXXX END XXXXXXXXXXXXXXXXXXXXXXXX

INSPECTION
REFERENCE
DATA

DATE

DATE

Date:5-23-2002

Beechcraft MOD:95-55 S/N:TC-157 REG:N1357Z

Installed Garmin: GMA-340, GNC-430, GNC-250XL, GXP-327, GA-56,
GA-56, ACK: A-30, GARMIN: GL106, Collins: ind-351

All units tested to and meet Mfr's specs this date.
Weight and balance updated. Equipment list updated.
F.A.A. form 337 filled out and Field Approval obtained.
Details on file at this repair station on INV. 5227 Dated 5/23/02.

Avionics Masters Inc.
5915 NW. 24th Way
Ft. Lauderdale, FL. 33309
FAA CRS VIMRO95K


KEN BORZAGE
2400994

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.						
	Airframe Log Entry Date: 06/01/02			N1357Z		
	Hour Meter: 3831.3			TTAF: 4340.7		
Completed Annual inspection this date and time I.A.W. Beechcraft 100hr/annual inspection guide and FAR 43 app. D. Lubricated all control attach points, pulleys, and bell cranks. Rotated pulleys 1/4 turn. Performed gear retraction test and checked all gear rigging. Performed manual gear extension test. Lubricated all gear fittings. Re-packed/inspected all main gear bearings. Installed new 500-5 nose tire and tube. Serviced main gear struts and brake system as per maintenance manual. C/W AD 72-22-01, ED-10/25/72 by lubrication, DUE H/M:3931.3 Installed new ELT battery, P/N2020, DUE 10/03. Operational check of aircraft systems and ELT per 91.207 OK. AD 01-23-10 N/A by installation. AD 90-18-14 due H/M 4818.9. This airframe has been inspected IAW an ANNUAL inspection this date. AD's current through 01-23-10. Aircraft determined to be in an airworthy condition. Owner notified Pitot Static/Transponder Check is due.						
Signed: <u>Eric Vaughn</u>						
Eric Vaughn A&P 493807814 IA						
TOTALS						

Used by a certificated

agency with name, rating and cert. no.

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
	Airframe Log Entry Date: 06/01/03			N1357Z		
	Hour Meter: 3831.7			TTAF: 4341.1		
Completed Annual inspection this date and time I.A.W. Beechcraft 100hr/annual inspection guide and FAR 43 app. D. Lubricated all control attach points, pulleys, and bell cranks. Rotated pulleys 1/4 turn. Performed gear retraction test and checked all gear rigging. Performed manual gear extension test. Lubricated all gear fittings. Installed new 650-8 right main gear tire supplied by owner. Serviced main gear struts and brake system as per maintenance manual. Replaced o-rings in left brake caliper C/W AD 72-22-01, ED-10/25/72 by lubrication, DUE H/M:3931.7 ELT battery DUE 10/03. Operational check of aircraft systems and ELT per 91.207 OK. AD 01-23-10 N/A by installation. AD 90-18-14 due H/M 4818.9. This airframe has been inspected IAW an ANNUAL inspection this date. AD's current through 01-23-10. Aircraft determined to be in an air worthy condition. Owner notified Pitot Static/Transponder Check is due.						
Signed: <u>Eric Vaughn</u>						
Eric Vaughn A&P 493807814 IA						

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	10-21-03	3:54	2.4	Hobbs	Removal defective Encoder	ACK A30 S/N 7031
	Revised Transponder to: D120-P2-T encoder S/N 22227, Matched Encoder					
	to: Garmin S/N 5027 altimeter. WT & balance change N/A.					
	:	I certify that the altimeter, static system, transponder, and altitude reporter test required by FARs 91.411, 91.413 & 91.217 have been performed and found to be within the limits of FAR 43 appendices E & F and AC 43.6a TESTED TO 20,000				
	:	Altimeter Model <u>Garmin</u> #1 S/N <u>5027</u> Model <u>X</u> #2 S/N <u>X</u>				
	:	Transponder Model <u>GTX327</u> #1 S/N <u>83706055</u> Model <u>X</u> #2 S/N <u>X</u>				
	:	Altitude Model <u>D120-P2-T</u> #1 S/N <u>22227</u> Model <u>X</u> #2 S/N <u>X</u>				
	:	SIGNED <u>Atx. W.</u>				
	:	NORTH STAR AVIATION, INC. Mankato, MN 56001				
	:	FAA CRS# NUTR521L W/O# <u>4111</u>				
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

INSPECTION
REFERENCE
DATA

S/N 7031
encoder

S
i-

ertificated

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

12/2/2003 Hobbs 3881.0

I certify the following work has been accomplished on this aircraft:

- Installed two EDM 800 units S/N 18712 and S/N 18698. Installation was done in accordance with JPI FAA approved installation manual for the EDM #103 Rev-C and STC #SA2586NM and SA00432SE.
- Installed GAMInjectors Kit No. GAD12B S/N 11991 on Right engine in accordance with STC No. SE09217SC. Installation was done in accordance with General Aviation Modifications, Inc. Installation Procedure, NO. IP-96-001 (Rev. 004).
- Installed GAMInjectors Kit No. GAD12B S/N 11990 on Left engine in accordance with STC No. SE09217SC. Installation was done in accordance with General Aviation Modifications, Inc. Installation Procedure, NO. IP-96-001 (Rev. 004).

Aircraft was test flown and checked for leaks.

Garmin
APP 901786761

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
12/2/2003				Reinforced elt and installed new ELT Ameri-King		
				AK:450 S/N 462811. Wt + Bal negligible. Batteries Due		
12/2005				C. M. M. A. 50178676		
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

July 12, 2004 Hobbs 4024.6 TT 4534.0

I certify that this airframe has been inspected IAW an annual inspection and was determined to be in airworthy condition. The following work performed:

AD 72-22-01 Complied with By lubrication of up lock rollers next due Hobbs 4124.6. AD 90-08-14 Complied with by Die Pen inspection of spar for cracks. Suggest re-check at next annual Next Due 07-09 or Hobbs 4524.6. AD 96-20-07 Complied with by disabling Janatrol heater system (caped fuel line at fuel pumps, disconnected wires at igniter and fan, placarded inop). Installed new air filters P/N BA-7605 on both engines. Installed new break linings P/N 04400 on right main gear. Rebuilt Right Break caliper. Installed new uplock cable P/N35-815109 on right gear. Installed serviceable shimmy dampener. Performed ELT annual. Flight controls, cables, hinges, inspected and lubricated as required. Inspected fuel lines, tanks, and caps, all systems checked normal.

Paul Stewart
Paul Stewart A&P 2776232 IA

DA

BR

FW

July 22, 2005 Hobbs 4106.5 TT 4615.9

I certify that this airframe has been inspected IAW an annual inspection and was determined to be in airworthy condition. The following work performed:

- AD 72-22-01 Complied with By lubrication of up lock rollers. Next Due Hobbs 4206.5
- AD 90-08-14 Complied with by Die Pen inspection of spar for cracks. Allowable crack found in right side foreword web face, protruding upward from the most outboard huckbolt in the bottom row. Next Due Hobbs 4206.5
- AD 96-20-07 Complied with by pressure decay test of combustion heater. Next due hh 810.0 or 07/07
- Removed both engines, overhauled and reinstalled right engine S/N CS-91965-5-L and left engine S/N CS-155839-8-L.
- Installed new Lord mounts P/N J9613-5 and new AN7-41A bolts on left engine.
- Installed new BA7610 air filters.
- Installed new AAD9-18-1 suction air filter.
- Installed Overhauled G455 wet vacuum pump, S/N 18529 from quality aircraft accessories on left engine.
- Installed retread 6.5x8 tires on both main gear.
- Installed one new 214-00100 and 124-00200 bearing and cone set on left main gear.
- Installed all new flexible fuel, oil, suction and instrument lines.
- Installed new 1524 nav light bulb on left wing tip.

-----continued next page-----

mechanic or repair agency with name, rating and cert. no.

CTION
ENCE
TA

ficated

CTION
ENCE
TA

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

- Installed new windshield manufactured by Lee Bailey's aircraft plastics.
- Both propellers overhauled by Maxwell Aircraft Service Inc.
- Installed CS1002 Prop-Guard on both propellers in accordance with STC # SP00582NY.
- Installed new carpet from Airtex Products, Inc.
- Performed ELT annual.
- Flight controls, cables, hinges, inspected and lubricated as required. Inspected fuel lines, tanks, and caps, all systems checked normal.
- 2 hour break in flight performed.
- Adjusted oil pressure and suction.
- Adjusted fuel and Idle control IAW Continental SID97-3C.

Paul Stewart A+P 2776232 IA



EQUIPMENT LIST

September 15, 2007 Hobbs 4170.5

I Certify that this airframe has been inspected in accordance with an annual inspection and the following work was performed.

- AD 2007-08-08 Complied with by lubrication of up lock rollers. Next Due Hobbs 4270.5
- AD 90-08-14 is due at Hobbs 4257.2
- AD 96-20-07 Complied with by pressure decay test of combustion heater. Next due 09/09
- Inspected ELT in accordance with FAR 91.207 par D.
- Lubricated all control attach points, pulleys, and bell cranks.
- Performed gear retraction test and checked all gear rigging. Performed manual extension test. Lubricated gear attach points and other lubrication points.
- Serviced wheels and brakes. Installed new o-rings on left main caliper.
- All AD's checked and current to this date. See compliance records

I certify that this airframe has been inspected in accordance with an annual inspection and determined to be in airworthiness condition. *Cam Johnson H-P 28006087A*

EQUIPMENT LIST

A/C SPEC
NUMBER

NAME, MAKE, MODEL, SERIAL NO.
MFG.

REQUIRED
OP

DATE

MAKE: Beechcraft
MODEL: 95-55
S/N: TC-157
REG. NO: 1357Z
WORK ORDER:
4682-01-2010

Airframe Entries

THE ALTIMETER, ALTITUDE REPORT
AND FOUND TO COMPLY WITH FAR
AS REQUIRED BY F.A.R. 91.413 AND

#1 ADC ALTIMETER

MODEL *Garwin* S/N *50*

CERTIFIED TO: *20,000* FEET

TRANS. #1 MODEL *GA-327*

ENCODER #1 - MODEL *D120*

DATE: 1/12/2010

MR485K GEG IFR CERTIFICATION/NON-PRESSURIZED AIRCRAFT

Page 2 of 3

ALTIMETER

FEET	Hg/in	TOLERANCE	ALTIMETER	ERROR
-1,000	31.018	+/- 20	-1.010	10
0	29.921	+/- 20	-10	10
500	29.385	+/- 20	490	10
1,000	28.856	+/- 20	990	10
1,500	28.335	+/- 25	1,490	10
2,000	27.821	+/- 30	1,980	20
3,000	26.817	+/- 30	2,990	10
4,000	25.842	+/- 35	3,980	20
6,000	23.978	+/- 40	5,970	30
8,000	22.225	+/- 60	7,960	40
10,000	20.577	+/- 80	9,950	50
12,000	19.029	+/- 90	11,950	50
14,000	17.577	+/- 100	13,950	50
16,000	16.216	+/- 110	15,940	60

FRICTION

FEET	TOLERANCE	READING
1,000	+/- 70	30
2,000	+/- 70	20
3,000	+/- 70	30
5,000	+/- 70	30
10,000	+/- 80	40
15,000	+/- 90	50
20,000	+/- 100	60
25,000	+/- 120	
30,000	+/- 140	

CASE LEAK

FEET	TOLERANCE	RESULTS
18,000	+/- 100	25 FPM

[illegible]

Good year
Fuel cell

76

SERVICEABLE

INSTRUMENT	COMPONENT NAME
MPFR. Goodell	Fuel Cell

PART 35-380135-9
NO.

73-9662

The aircraft component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency and is approved for return to service.

Pertinent details of the repair are on file at this repair station under

WORK ORDER NO. 3744

7-23-76

DATE 11-23-12 SIGNED Gerry Trug AND TECH SERVICES

AIR-TECH SERVICES
8147 Secura Way
Santa Fe Springs, California
F.A.A. Certificated Repair
Station No. 4758



AIRFRAME MAINTENANCE RECORDS

Log No. 3

Aircraft Registration No. 1357Z

Aircraft Mfg. Beech Model Baron 95-55 Serial No. TC-157

LH Engine Mfg. Continental Model 10-470-L Serial No. C8-155839-8-L

RH Engine Mfg. Continental Model 10-470-L Serial No. C8-91965-5-L

LH Propeller Mfg. Hartzell Model PHC-C3YF-2UF Serial No. _____

Hub Design No. BE Hub Serial No. EB544

Blade Design No. FC7663-2R Blade Serial No's. C94712

C94716

C94728

RH Propeller Mfg. Hartzell Model PHC-C3YF-2UF Serial No. _____

Hub Design No. _____ Hub Serial No. EB545

Blade Design No. FC7663-2R Blade Serial No's. C92225

C94730

C94697

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965


(631) 765-9375

1-800-235-6444

FAX: (631) 765-9359

© 1979 AeroTech Publications Inc.

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	------------------------------	---



Moody Aviation
Building #68
6719 E. Rutter Ave.
Spokane, WA 99212
Phone: (509) 535-4051

Airframe Logbook Record

Registration:	N1357Z	Date:	8 April 2010
Aircraft Model:	Baron 95-55	Hobbs Time:	4185.0
Aircraft Serial Number:	TC-157	Airframe Total Time:	4694.4
		Work Order No:	7Z0309

Performed an annual inspection with reference to manufacturer's service manual P/N 55-590000-13 Reissue G, July 1, 2009. The following work was performed:

- AD64-10-03 eff date 5 June 1964. Inspected seat belt buckles IAW para a, 1, 2. No deficiencies found. Next Due Aircraft TT 4794.4
- AD72-11-02 eff date 20 May 72 Inspection of fuel tanks for baffles. CW Par B 1) of this AD. No Baffles found.
- AD76-07-12 eff date 30 Aug 1977. Performed ignition switch grounding check IAW the AD and TCM SB 583 Part 2, Procedure B. Next Due Aircraft TT 4794.4
- AD78-05-06 eff date 30 June 1978. Not applicable by Inspecting L aux fuel tank IAW Beech SI 0895 Step 1 to determine manufacturer. Tank is NOT Goodyear, therefore AD does not apply. No further action necessary.
- AD89-05-02 eff date 24 Mar 1989. Determined Right elevator fitting IS magnesium. Inspected IAW AD para a,b, and Beech SB 2242 Rev I Fig 1. No cracks found. Right elevator only. Next Due Aircraft TT 4794.4
- AD90-08-14 eff date 7 May 1990. Inspected wing carry-through spar IAW Beech SB 2269 Rev I and AD 90-08-14. No change in existing allowable crack (see log 22 July 2005). Next Due Aircraft TT 4794.4
- AD91-17-01 eff date 25 Nov 1991. Complied with para b and c by painting LH elev trim tab housing blue and RH housing black. No further action necessary.
- AD2007-08-08 eff date 25 May 2007. Complied with para e, 1 & 4 by lubricating uplock rollers. Next Due Aircraft TT 4794.4
- AD2009-19-07 C2 eff date 7 Oct 2009. Performed log book inspection for EQ3 cyl Par g. IAW TCM MSB09-1B dated July 14, 2009 none found. No further action required.
- Verified accuracy of RH and LH oil pressure gauges.
- Installed new low voltage light bulb, P/N GE327.
- Installed new bushings P/N 496-1, in LH elevator middle and outboard hinges. Cleaned and inspected elevator push pull rods and attach fittings. Reinstalled L elevator. Torqued IB and middle hinge point to 30 inlbs, attach fitting to 70 in-lbs, saftied. Ops check okay.
- Repacked L and R main gear bearings. Installed new Timken bearing and cone P/Ns 13836 and 13889, and new tube P/N 6.5x 7.0 x 8 in R main. Torqued wheel halves to 150inlbs. Reinstalled, torqued, and saftied.
- Repacked nose wheel bearings. Installed new 5.00 x 5 tube. Torqued wheel halves to 83 in-lbs. Reinstalled and saftied
- Disassembled, cleaned R and L brake caliper assemblies. Installed new O-rings, P/N MS28775-222.
- Reassembled brakes, torqued brake back plates to 90 in-lbs.
- Fabricated flexible brake hoses out of MIL-H-8794-4 hose. Right main lower hose, left main upper hose. Pressure tested hoses. Leak check ok.
- Drained, disassembled, cleaned, reinstalled brake fluid reservoir. Leak check OK.
- Installed new O-rings, P/Ns MS28775-010,-112,-111, in both pilot's master cylinders and outboard co-pilots master cylinder. Installed new 3502-18-34 spring washer in co-pilots cyl. Reinstalled, saftied the mounts and torque hose fittings. Leak check OK.
- Bled brake system.
- Installed serviceable nose gear Braze Assy P/N 35-825195-21, new brass bearing P/N 45-825031. Installed new O-rings MS28775-223,-224, MS28778-011, and new scraper ring P/N MS28776R2-19. Reassembled and installed on aircraft. Torqued mounting bolts to 14 ft-lbs. Serviced nose strut.
- Cleaned and reinstalled L and R fuel strainers. Saftied.
- Performed ELT Annual IAW 14CFR91.207 and Moody checklist. NEXT DUE: April 2011.
- Installed new Duracell PC1300 batteries in ELT. NEXT DUE: April 2011.
- Performed gear retraction. Increased L and R uplock cable tensions, saftied. Adjusted L main uplock block.
- Installed new fuel sump valve P/N CCA3400 (L wing, forward) and new sump valve P/N CCA4850 (R wing aft sump).
- Installed new AN4-15A bolts and MS21042L4 nuts on seat belt mount, middle seat
- Installed new AN470AD4-12 rivet in L flap inboard attach bracket, straightened R flap inboard attach bracket.
- Installed "No Step" placards on right wing.
- Adjusted L & R mixture cable rod ends, L & R prop control rod ends, and L throttle rod end to obtain full control travel.
- Adjusted rudder cable tension, elevator trim cables tension, saftied turnbuckles.
- SI 0694-311r1 Secured hat shelf insulation with 1300L Scotch contact cement.
- Adjusted rudder stop bolts to obtain correct travel.
- Adjusted rudder trim stops to obtain correct travel.
- Installed new AN3 bolt on LH elevator trim tab connection, saftied.
- Fabricated and installed new anti-ice line out of 5056 .25 OD aluminum tubing. RH wing root to engine nacelle.
- Fabricated section of fuel line out of 5056-0 .035 tubing. From left wing root to fuel selector valve. Leak check ok
- Installed 4 new bonding straps on elevator.
- Installed new ground wire at GPU connection. Stop drilled crack and installed 2024-T3 .040 backing plate.
- Serviced shimmy damper ops check ok.
- Installed Oxygen cylinder hydrostatically tested By Oxarc Inc. Next Hydrostatic Due -- Nov. 2014.
- Sealed leaks in static system, leak check OK.

Work performed by: Matt Scheer, Steve Thimsen, J. Ericsson, Jonathan Santhouse, Lance Erickson, Laura Cahill, Aaron Stocks, Amos Simiyu, Mark McIntire, Tim Hurley, Kars Kroneman, Peter Stuart, Jason Floyd, Jonathan Schultz

I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

SIGNED

A&P 3331673 IA

SUB-TOTAL this page

TOTAL—Carry forward to next page

TOTAL—Carry forward to next page



ENGINE MAINTENANCE RECORDS

Log No. 3Aircraft Registration No. 1357ZEngine Manufacturer ContinentalModel 10-470-LSerial No. C8-155839-8-LDate installed on aircraft 22-JUL-05 (014)Time Between Overhauls (TBO) 1500 Hours

If used on multi-engine aircraft:

☐ Right	☒ Left
☐ Front	☐ Rear

**AEROTECH PUBLICATIONS INC.**

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

Engine Record General Information

Manufacturer CONTINENTAL **Model** I O-470-L

Serial CS-155839-8-L **Type Certificate** _____

This engine is currently installed in aircraft: N 1357Z Left

Minimum Octane Fuel _____ **Oil Grade** Summer _____ Winter _____

Magneto Time _____ **Point Setting** _____ **Firing Order** _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ **hours**

July 22, 2005 Hobbs 4106.5 SMOH 0 TT 1595.0 S/N CS-155839-8-L

- Removed engine from aircraft, removed cylinders and accessories. Case sent in and the following work was performed by Bolduc Aviation Specialized Services, Inc:
 - Clean and Zyglo case – rejected.
 - Bore check and inspect case.
 - Modified through bolts, 10 ea.
 - Clean, magnaflux and inspect/runout crank. Send for repair
 - Rebush and line bore counterweights Cont. 2 sets
 - Install counterweights and preserve crankshaft, 2 sets.
 - Rebush and line bore rods, 6 ea.
 - Clean and magnaflux misc. steel parts
 - Rebush-bore-reface rocker arms, 12 ea.
 - Balance crankshaft and connecting rods
 - Overhauled starter adapter
 - Assembled crankshaft, crankcase, oil sump, starter adapter, and oil sump only . Did not install cylinders.
- Installed 6 new SA539467 piston pins.
- Installed 6 overhauled 628488 lifters and 6 overhauled SA 628488 lifters.
- Installed 6 new AEC 631397 cylinder assemblies with AEC 470-T2 seal kits.
- FCU/throttle body P/N 625219-2 overhauled by Mike's A/C Fuel Metering Service, Inc. (HK2R875JK)
- Fuel pump P/N 638156-3 overhauled by America's Fuel Systems, LLC.
- Fuel manifold P/N 631427 S/N M2419 overhauled by America's Fuel Systems, LLC.
- Push rods and rockers checked and rebushed by Bolduc.

-----continued next page-----

ons
of
s.)

L ENG

4/10


ons
if
s.)

ions
r of
ies.)

- Installed engine with new Lord mounts P/N J9613-5 and new AN7-41A bolts.
- Installed new fittings AN914-1, MS20822-4, AN816-4, AN912-1 on fuel pump.
- Installed new surplus 628005 generator pulley from Preferred air parts.
- Installed overhauled starter P/N MHJ-4003 S/N 12D000066 from Aerotech of Louisville, Inc.
- Installed overhauled generator P/N 1105056 S/N A504078 from Aerotech of Louisville, Inc.
- Installed new BL600606-1 (S6RSC-201) and BL6006056-1 (S6RSC-205) magnetos.
- Installed new CH11730 ignition harness.
- Installed new 627681 throttle body bracket.
- Installed new 539547-30.00 generator belt.
- Installed overhauled G455 wet vacuum pump, S/N 18529 from Quality Aircraft Accessories.
- Installed all new flexible fuel, oil, suction and instrument lines.
- Propeller overhauled by Maxwell Aircraft Service Inc.
- Serviced with 12 Qts. Aeroshell 80 straight mineral oil.
- Timing checked per TC. Inspected all accessories, prop, spinner, engine mounts. Run up check good.
- 2 hour break in flight performed.
- Adjusted oil pressure and suction.
- Adjusted fuel flow and idle RPM IAW Continental SID97-3C.

I certify that this engine has been inspected IAW an annual inspection and was determined to be in airworthy condition.

Paul Stewart A+P 2776232 IA



[illegible]

rations
ber of
entries.)

YEAR _____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-----------------------	---------------------------	-------------------	-----------------------------	---

August 18, 2006 Hobbs 4157.2 SMOH 50.7

I certify that this engine has been inspected in accordance with an annual inspection and the following work was performed.

- Hot compression check with the following results #1 78/80, #2 76/80, #3 76/80, #4 76/80, #5 76/80, #6 77/80.
- Drained oil, removed oil screen, cleaned and reinstalled. Torqued and safitied. Serviced with 11 quarts of Aeroshell 15W50.
- Cleaned and rotated spark plugs. Checked and lubricated engine control linkages.
- Installed new bracket air filter
- Checked magneto timing per type certificate
- Inspected all accessories, prop, spinner, engine mounts, wiring, and baffling.

I certify that this engine has been inspected in accordance with an annual inspection and determined to be in airworthiness condition. *James Egan - A41 501781676*

Common Item #1 50186761 PA

YEAR

DATE



ENGINE MAINTENANCE RECORDS

Log No. 3Aircraft Registration No. 1357ZEngine Manufacturer ContinentalModel 10-470-LSerial No. C8-155839-8-LDate installed on aircraft 22-JUL-05 (04)Time Between Overhauls (TBO) 1500 Hours

If used on multi-engine aircraft:

☐ Right	☒ Left
☐ Front	☐ Rear

**AEROTECH PUBLICATIONS INC.**

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---



Moody Aviation
Building #68
6719 E. Rutter Ave.
Spokane, WA 99212
Phone: (509) 535-4051

Left Powerplant Logbook Record

Registration:	N1357Z	Date:	8 April 2010
Aircraft Model:	Baron 95-55	Airframe Total Time:	4694.4
Aircraft Serial:	TC-157	Engine Total Time:	1673.5
Engine Model:	IO-470L	Engine SMOH:	78.5
Left Engine Ser Number:	CS-155839-8-L	Work Order No:	7Z0309

Performed an annual inspection with reference to manufacturer's service manual P/N 55-590000-13 Reissue G, July 1, 2009. The following work was performed:

Compression Check

#1 73/80	#2 75/80	#3 77/80	#4 71/80	#5 73/80	#6 72/80
----------	----------	----------	----------	----------	----------

- AD2009-19-07 C2 eff date 7 Oct 2009. Performed log book inspection for EQ3 cyl Par g. IAW TCM MSB09-1B dated July 14, 2009 none found. No further action required
- AD70-14-07 eff date 22 Nov 74 Complied with by inspecting pump IAW par A of this AD.
- Cleaned, gapped, tested, reinstalled and torqued spark plugs to 360 inlbs.
- Inspected oil screen, cleaned, reinstalled with new AN 900-27 gasket, torqued to 150 in lbs and safetied. Serviced with 10 qts Aeroshell 15W50. No leaks.
- Adjusted fuel flow and idle RPM IAW Continental SID97-3C.
- Inspected fuel screen, cleaned, reinstalled with new gasket P/N 649983, torqued 120 inlbs, safetied.
- Installed new Brackett air filter P/N BA7610
- Fabricated and installed new baffling piece behind cyl#2. Used 2024 T3 .040 aluminum.
- Fabricated bottom section of crankcase breather tube with S052-TO aluminum.
- Patched baffling crack behind cyl#1 with 2024 T3 .032 aluminum.
- Cleaned and reinstalled vacuum relief valve filter
- Cleaned and reinstalled Gamijectors, torqued to 60 in lbs, and fuel lines to 45 in lbs. Leak check ok
- Adjusted Idle Mixture 1/4 turn rich.
- Installed 2 new gaskets P/N 10-400613 on R and L magnetos. Torqued mounting nuts to 120inlbs, verified correct timing.
- Tightened generator belt. Torqued adj. bolt to 175inlbs, safetied.
- Cleaned prop anti-ice orifice, pressed orifice back into tubing, repositioned tube to avoid rubbing on slinger ring.
- Fabricated new access cover in air box (for generator adjustment) out of 2024 T3 alum. Reinstalled airbox.
- SB 96-7 Retorqued engine mount nuts to 325 in-lbs.

Work performed by: Matt Scheer, Steve Thimsen, J. Ericsson, Jonathan Santhouse, Lance Ericsson, Laura Cahill, Aaron Stocks, Amos Simiyu, Mark McIntire, Tim Hurley, Kars Kroneman

I CERTIFY THAT THIS POWERPLANT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

SIGNED

A&P 3331673 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

ENGINE MAINTENANCE RECORDS

Log No. 4

Aircraft Registration No. 1357Z

Engine Manufacturer Continental

Model 10-470-L

Serial No. C8-91965-5-L

Date installed on aircraft 22-JUL-05 (OH)

Time Between Overhauls (TBO) 1500 Hours

If used on multi-engine aircraft:

☒ Right ☐ Left
☐ Front ☐ Rear



AEROTECH PUBLICATIONS INC.

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

Engine Record General InformationManufacturer Continental Model IO-470-LSerial CS-91965-5-L Type Certificate _____This engine is currently installed in aircraft: N13522 Right

Minimum Octane Fuel _____ Oil Grade Summer _____ Winter _____

Magnetos Time _____ Point Setting _____ Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ hours

July 22, 2005 Hobbs 4106.5 Smoh 0 TT 3270.2 S/N CS-91965-5-L

- Removed engine from aircraft, removed cylinders and accessories. Case sent in and the following work was performed by Bolduc Aviation Specialized Services, Inc:

Bore check and inspect case. Hone to size.
 Modified through bolts, 10 ea.
 Clean, magnaflux and inspect/runout crank
 Rebush crankshaft blades, 2 sets
 Polish crankshaft
 Install counterweight and preserve crankshaft, 2 sets
 Ultrasonic inspect per Cont. Ad#M97-26-17
 Rebush and line bore rods, 6 ea.
 Clean and magnaflux misc. steel parts
 Rebush-bore-reface rocker arms, 12 ea.
 Balance crankshaft and connecting rods
 Overhauled starter adapter
 Assembled crankshaft, crankcase, oil sump, starter adapter, and oil sump only. Did not install cylinders.

- Installed 6 new 539467 piston pins.
- Installed 6 overhauled 628488 lifters and 6 overhauled SA 628488 lifters.
- Installed 6 new AEC 631397 cylinder assemblies with AEC 470-T2 seal kits.
- FCU/throttle body P/N 625219-2 overhauled by Mike's A/C Fuel Metering Service, Inc. (HK2R875JK)
- Fuel pump P/N 638156-3 overhauled by America's Fuel Systems, LLC.
- Fuel manifold P/N 631427 S/N 631427 overhauled by America's Fuel Systems, LLC.
- Push rods and rockers checked and rebushed by Bolduc.

-----continued next page-----

ons
of
es.)

ons
of
es.)

- Propeller governor P/N 210355JFRSAA overhauled by Maxwell Aircraft Service.
- Installed new fittings AN914-1, MS20822-4, AN816-4, AN912-1 on fuel pump.
- Installed overhauled starter P/N 1108234 S/N 74390 from Aerotech of Louisville, Inc.
- Installed overhauled generator P/N 1105056 S/N A505013 from Aerotech of Louisville, Inc.
- Installed new BL600606-1 (S6RSC-201) and BL6006056-1 (S6RSC-205) magnetos.
- Installed new CH11730 ignition harness.
- Installed oil cooler P/N 1E1104 overhauled by Pacific Oil Cooler Service, Inc.
- Installed all new flexible fuel, oil, suction and instrument lines.
- Propeller overhauled by Maxwell Aircraft Service Inc.
- Serviced with 12 Qts. Aeroshell 80 straight mineral oil.
- Timing checked per TC. Inspected all accessories, prop, spinner, engine mounts. Run up check good.
- 2 hour break in flight performed.
- Adjusted oil pressure and suction.
- Adjusted fuel flow and idle RPM IAW Continental SID97-3C.

I certify this engine has been inspected IAW an annual inspection and was determined to be in airworthy condition.

Paul Stewart A+P 2776232 IA



ons
of
s.)

R 63A 3/9

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		January 11, 2006		
		Hobbs 4128.9 Smoh 22.4 TT 3292.6		
		Drained oil serviced with 11 qts. Aeroshell 15W50 oil.		
		Removed and inspected oil filter. Re-installed oil filter		
		torqued and saftied.		
		Joel LaBouef		A&P 2919180
				
		March 23, 2006 Hobbs 4144.3 Smoh 37.8 TT 3308.0		
		Drained oil and serviced with 11 qts. Aeroshell		
		15W50. Removed and Inspected oil filter.		
		Re-installed torqued and saftied.		
		Ross Charlton		A&P 2746303
				

YEAR
DATE
Aug
I c fol
I c d3

ations
er of
ntries.)

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------	---------------------------	-------------------	-----------------------------	---

August 18, 2006 Hobbs 4157.2 SMOH 50.7

I certify that this engine has been inspected in accordance with an annual inspection and the following work was performed.

- Hot compression check with the following results #1 68/80, #2 78/80, #3 78/80, #4 78/80, #5 74/80, #6 78/80.
- Drained oil, removed oil screen, cleaned and reinstalled. Torqued and safitied. Serviced with 11 quarts of Aeroshell 15W50.
- Cleaned and rotated spark plugs. Checked and lubricated engine control linkages.
- Installed new bracket air filter
- Checked magneto timing per type certificate
- Inspected all accessories, prop, spinner, engine mounts, wiring, and baffling.

I certify that this engine has been inspected in accordance with an annual inspection and determined to be in airworthiness condition. *Comm John ADG01786761IA*

R 007 7/9

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------	---------------------------	-------------------	-----------------------------	---

YEAR
DATE

September 15, 2007 Hobbs 4170.5 SMOH 74.0

I certify that this engine has been inspected in accordance with an annual inspection and the following work was performed.

- Hot compression check with the following results #1 74/80, #2 78/80, #3 78/80, #4 78/80, #5 74/80, #6 78/80.
- Drained oil, removed oil screen, cleaned and reinstalled. Torqued and safitied. Serviced with 11 quarts of Aeroshell 15W50.
- Cleaned and rotated spark plugs. Checked and lubricated engine control linkages.
- Installed new bracket air filter BA7605
- Checked magneto timing per type certificate
- Inspected all accessories, prop, spinner, engine moun:s, wiring, and baffling.

I certify that this engine has been inspected in accordance with an annual inspection and determined to be in airworthiness condition.

Cameron Delmon AIP 2800608 IA

July 24, 2008 Tach 4176.2

Removed oil pump assembly and installed overhauled oil pump assembly as provided by Bolduc Aviation Services under work order # 22567. Ran engine and checked for leaks. Aircraft is approved for return to service

Cameron Delmon AIP 2800608 IA

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
END SEE LOG #4				

LOG 4

AD106

RT. Eng 9

DATE

TOTAL
TIME
IN
SERVICETOTAL
TIME
SINCE
OVERHAULTACH OR
RECORDING
METER
TIMEDESCRIPTION OF WORK PERFORMED—
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

Moody Aviation
Building #68
6719 E. Rutter Ave.
Spokane, WA 99212
Phone: (509) 535-4051

TOTALS brought forward from previous page
Right Powerplant Logbook Record

Registration:	N1357Z	Date:	8 April 2010
Aircraft Model:	Baron 95-55	Airframe Total Time:	4694.4
Aircraft Serial:	TC-157	Engine Total Time:	3348.7
Engine Model:	IO-470L	Engine SMOH:	78.5
Right Engine Ser Number:	CS-91965-5-L	Work Order No:	7Z0309

Performed an annual inspection with reference to manufacturer's service manual P/N 55-590000-13 Reissue G, July 1, 2009. The following work was performed:

Compression Check

#1 74/80	#2 76/80	#3 77/80	#4 77/80	#5 76/80	#6 78/80
----------	----------	----------	----------	----------	----------

- AD2009-19-07 C2 eff date 7 Oct 2009. Performed log book inspection for EQ3 cyl Par g. IAW TCM MSB09-1B dated July 14, 2009 none found. No further action required
- AD70-14-07 eff date 22 Nov 74 Complied with by inspecting pump IAW par A of this AD.
- Installed overhauled engine-driven fuel pump, P/N 638156-3, S/N 21563, OH'd by Aircraft Accessories, WO#s 40463 and 40665, dated 2/9/10 and 2/25/10. Torqued mounting nuts to 160 in-lbs with new lock washers, P/N MS35333-42 (4). Tensioned generator belt to 3/8" deflection @ 10 lbs, torqued mounting and adjustment bolts to 140 in-lbs and safetied adjustment bolt. Installed LH intake tube with 4 hose clamps. Connected 4 fuel lines to pump and fuel line to fuel manifold and torqued. Installed test fittings and gauges and torqued. No leaks. Checked low psi unmetered @ 600 RPM @ 9 psi (9-11 range) and high metered psi @ 2625 RPM @ 15.5 psi (15 - 17.5 range) IAW TCM SID 97-3E. Removed test fittings and torqued fuel lines. No leaks.
- Installed Engine Data plate Engine S/N CS-91965-5-L with reference to TCM SIL -00-9 riveted on
- Cleaned, gapped, tested, reinstalled and torqued spark plugs to 360 inlbs.
- Inspected oil screen, cleaned, reinstalled with new AN 900-27 gasket, torqued to 150 in lbs and safetied. Serviced with 10 qts Aeroshell 15W50. No leaks.
- Adjusted fuel flow and idle RPM IAW Continental SID97-3C.
- Inspected fuel screen, cleaned, reinstalled with new gasket P/N 649983, torqued 120 inlbs, safetied.
- Installed new Brackett air filter P/N BA7610
- Cleaned and reinstalled vacuum relief valve filter
- Installed injector boss bushing in cyl #3 IAW ECI Service Instruction 99-8-1, para 10.7.4. Cleaned and reinstalled Gami injectors, torqued to 60 in lbs, and fuel lines to 45 in lbs. Leak check ok.
- Installed serviceable generator mount P/N 628004. Reinstalled engine mount and torqued mount-to-engine bolts to 300inlbs, mount-to-frame bolt to 225inlbs. Torqued the other 3 lower engine mount bolts to 225inlbs. Installed generator, torqued mounting bolts to 190inlbs, set belt tension, torqued adj. bolt to 175inlbs and safetied. Reinstalled air box.
- Repositioned front engine mount Lord mount bushing and torqued bolt to 290 in-lbs.

Work performed by: Matt Scheer, Steve Thimsen, J. Ericsson, Jonathan Santhouse, Lance Ericsson, Laura Cahill, Aaron Stocks, Amos Simiyu

I CERTIFY THAT THIS POWERPLANT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

SIGNED

A&P 3331673 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

M. Map 1 of 1



PROPELLER MAINTENANCE RECORDS

Log No. 3

Aircraft Registration No. 1357Z

Propeller Manufacturer Hartzell

Hub Model PHC-C3YF-2UF

Blade Design No. FC7663-2R

Hub Serial No. EB544

Blade Serial No's.

1. C94712
2. C94716
3. C94728
4. _____

Pitch Range:

High _____ Low _____

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft 22-JUL-05 (OH)

Time Between Overhauls (TBO) 2000 Hours

If used on multi-engine aircraft:

- | | |
|--------------------------------|--|
| ☐ Right | ☒ Left |
| ☐ Front | ☐ Rear |



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC.

www.adlog.com
P.O. Box 1359 / Southold, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				



Moody Aviation
Building #68
6719 E. Rutter Ave.
Spokane, WA 99212
Phone: (509) 535-4051

Left Propeller Logbook Record

Registration:	N1357Z	Date:	8 April 2010
Aircraft Model:	Baron 95-55	Airframe Total Time:	4694.4
Aircraft Serial:	TC-157	Propeller Total Time:	2155.5
Propeller Model:	PHC-C3 YF-2UF/FC7663-2R	Propeller SMOH:	78.5
Propeller Serial Number:	Hub- EB544 Blades-C94712,C94716,C94728	Work Order No:	7Z0309

Performed an annual inspection with reference to Beech service manual P/N 55-590000-13 Reissue G, July 1, 2009, and Hartzell Manual 115N Rev 14The following work was performed:

- Serviced with Aeroshell 5, dressed and painted propeller tips, inspected hub, back plate and blades, recharged hub with nitrogen to 17 psi.

Work performed by: Matt Scheer, Aaron Stocks

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

SIGNED

[Signature]

A&P 3331673 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		November 1, 1999 Hobbs 3799.9 N1357Z	
		LT. Propeller TSPOH 640.5	
		Removed spinner serviced with Aeroshell #5 grease, dressed propeller blades and inspected spinner backing plate. Reviewed and complied with AD's. This propeller is approved for return to service.	
		Kenneth J. Clarke <i>Kenneth J. Clarke</i>	
		A&P263178947 IA TSPOH 640.5	
		11/01/99 3799.9	
		CERTIFY THAT THIS Propeller HAS BEEN	
		INSPECTED IN ACCORDANCE WITH AN ANNUAL	
		INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY	
		CONDITION AND IS APPROVED FOR RETURN TO SERVICE	
		SIGNATURE: <i>Kenneth J. Clarke</i>	
		A & P (A) IA# 263178947 I 4	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	Propeller Log Entry Date: 06/01/02 TSMOH: 812.3	N1357Z Left Prop TTIS: 1880.3 Hour Meter: 3831.3	IRE
	Inspected propeller. Cleaned and dressed blade nicks. Visually inspected propeller hub, and greased all grease fittings. I certify that this propeller was inspected I.A.W. and ANNUAL/100 Hour inspection and found to be in an airworthy condition. Signed: <i>Eric Vaughn</i> Eric Vaughn A&P 493807814 IA		
	Propeller Log Entry Date: 06/01/03 TSMOH: 812.7 TTIS: 1880.7 N1357Z Left Prop Hour Meter: 3831.7 Inspected propeller. Visually inspected propeller hub, and greased all grease fittings. I certify that this propeller was inspected I.A.W. and ANNUAL/100 Hour inspection and found to be in an airworthy condition. Signed: <i>Eric Vaughn</i> Eric Vaughn A&P 493807814 IA		

SERVICEABLE

(COMPONENTS)

PROPELLER

HARTZELL

COMPONENT NAME

MFG. NAME

PHC-C3YE-2FU

EB544

MODEL or TYPE

SERIAL No.

☒ REPAIRED ☐ O'HAULED ☒ TESTED ☒ INSPECTED

The aircraft component identified above was repaired and/or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed.

Pertinent details of the repair are on file at this repair station under:

CUSTOMER AMERICAN AIRCRAFT SALES

DATE 5/2/91 TACH 3158.5W/O 2218

SIGNED FOR:

REDLANDS PROPELLER SERVICE, INC.

1625 Sessums Drive
Redlands, CA 92374

F.A.A. Certified Repair Station #REUR072K

PROPELLER MAINTENANCE RECORDS

Log No. 3

Aircraft Registration No. 1357Z

Propeller Manufacturer Hartzell

Hub Model PHC-C3YF-2UF

Blade Design No. FC7663-2R

Hub Serial No. EB545

Blade Serial No's.

1. C92225

2. C94730

3. C94697

4. _____

Pitch Range:

High _____ Low _____

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft 22-Jul-05 (OH)

Time Between Overhauls (TBO) 2000 Hours

If used on multi-engine aircraft:

☒ Right ☐ Left

☐ Front ☐ Rear

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965

(631) 765-9375

1-800-235-6444

FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page



Moody Aviation
Building #68
6719 E. Rutter Ave.
Spokane, WA 99212
Phone: (509) 535-4051

Right Propeller Logbook Record

Registration:	N1357Z	Date:	8 April 2010
Aircraft Model:	Baron 95-55	Airframe Total Time:	4694.4
Aircraft Serial:	TC-157	Propeller Total Time:	2234.0
Propeller Model:	PHC-C3YF-2UF/FC7663-2R	Propeller SMOH:	78.5
Propeller Serial Number:	Hub- EB545 Blades-C92225,C94730,C94697	Work Order No:	7Z0309

Performed an annual inspection with reference to Beech service manual P/N 55-590000-13 Reissue G, July 1, 2009, and Hartzell Manual 115N Rev 14. The following work was performed:

- Serviced with Aeroshell 5, dressed and painted propeller tips, inspected hub, back plate and blades, recharged hub with nitrogen to 17 psi.

Work performed by: Matt Scheer, Aaron Stocks

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

SIGNED [Signature]

A&P 333673 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

Inspected propeller. Cleaned and dressed blade nicks. Visually inspected propeller hub, and greased all grease fittings. I certify that this propeller was inspected I.A.W. and ANNUAL/100 Hour inspection and found to be in an airworthy condition. *S*

Signed: Eric Vaughn
Eric Vaughn A&P 493807814

SELLER SERVICE, INC.
Research Drive
Irvine, CA 92614
Repair Station #REUR072K

July 22, 2005 Hobbs 4106.5 Smoh 0
Reinstalled on N1357Z right engine.
Installed C51002 Prop-Guard in accordance with STC # SP00582NY
Paul Stewart A+P 2776232 IA

Customer	George Casada		
W.O. No.	1154	Serial No.	E545
Model	PHC-C3YF-2UF/FC7663-2R		
Parts Name	Hartzell propeller	Quantity	1

Remarks Prop completely overhauled. Steel parts
checked & cadmium plated. Hub body overhauled per Hartzell
S.I. 144A. Blade shanks checked, polished & compression
rolled to comply w/ S.B. 118C & A.D. 77-12-06 & S.B. 97A
Blades penetrant inspected, refinished, anodized & painted.
Prop assembled, checked, lubricated and balanced.

inspected, checked, lubricated and balanced.
Inspector Eduardo Enriquez Date 9-28-83

ent identified above was
acted in accordance with
of the Federal Aviation
approved for return to service
d.

HARTZELL
MFG. NAME
FU EB545
SERIAL No.

FEASIBLE

AC TT 4311 DATE: 4-10-01 TSOH 775
 REMOVED SPINNER INSPECTED PROP I/A/W BARRON 100 HOUR INSPECTION LIST AND FAR
 43 APP D CHECKED GOVERNOR FEATHER CHECK OK, PROP HAS BEEN INSPECTED I/AW
 ANNUAL INSPECTION AND HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION.
 A&P385842869I/A [Signature]

KI. Prop

7/4

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		November 1, 1999 Hobbs 3799.9 N1357Z RT. Propeller TSPOH 640.5	
		Removed spinner serviced with Aeroshell #5 grease, dressed propeller blades and inspected spinner backing plate. Reviewed and complied with AD's. This propeller is approved for return to service.	
		Kenneth J. Clarke <u>Kenneth J. Clarke</u>	
		A&P263178947 IA TSPOH 640.5	
		<u>11/01/99</u> <u>3799.9</u>	
		CERTIFY THAT THIS <u>Propeller</u> HAS BEEN	
		INSPECTED IN ACCORDANCE WITH <u>AN ANNUAL</u>	
		INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY	
		CONDITION AND IS APPROVED FOR RETURN TO SERVICE	
		SIGNATURE: <u>Kenneth J. Clarke</u>	
		A&P <u>263178947 IA</u>	

N1357Z Right Prop
Hour Meter: 3831.3

Propeller Log Entry Date: 06/01/02
TSMOH: 1008.7 TTIS: 1880.3



1698 Airport Road
Worthington, MN 56187
Phone 507.376.9293
Fax 507.376.3856

Date 12/2/2003
Owner Plains Planes Inc.
Address 727 Lake CT; Worthington, MN 56187
Make Beech 95-55
Serial Number TC-157
N Number N1357Z

ITEM	Weight	Arm	Moment
Previous Aircraft Empty Weight	3315.75	76.95	255145.25
Removed existing EGT wiring	-2	64	-128.00
Installed EDM 800 units	+6	64	+348.00
	<u>3319.75</u>	<u>76.93</u>	<u>255401.25</u>

New Empty Weight 3319.75

New Useful Load

New Empty Weight C.G. 76.93

New Moment 255401.25

Signature Cameron Johnson

Certificate Number 501786761 AHP

N1357Z
S/N TC-157

TODAY'S DATE
MODEL 95-55

12-May-10
HOBBS TIME
AC TOTAL TIME

4185.0
4694.4
RIGHT ENGINE TT
LEFT ENGINE TT

AR = AS REQUIRED

DATE INSTALLED	HOBBS TIME INSTALLED	AC TT @ INSTALL	PART TSO @ INSTALL	TSN @ INSTALL	INTERVALS YEARS HOURS	NEXT INSPECTION DUE	PART TSN TODAY	DUE @ HOBBS	DUE DATE	TIME REMAINING
22-Jul-05	4106.5	4615.9	0.0	3270.2	1500	RIGHT ENGINE TBO 100 HR	3348.7	5606.5	22-Jul-10	1421.5
22-Jul-05	4106.5	4615.9	0.0	1995.0	1500	HOSES WITH FLAMMABLE LIQUIDS	1673.5	5606.5	22-Jul-10	1421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	5	LH PROPELLER (HARTZEL)	78.5	6106.5	22-Jul-10	1921.5
22-Jul-05	4106.5	4615.9	0.0	2155.5	2000	RH PROPELLER (HARTZEL)	2234.0	6106.5	22-Jul-10	1921.5
22-Jul-05	4106.5	4615.9	0.0	0.0	2400	LH PROPELLER GOVERNOR	78.5	6506.5	22-Jul-10	2321.5
22-Jul-05	4106.5	4615.9	0.0	0.0	2400	RH PROPELLER GOVERNOR	78.5	6506.5	22-Jul-10	2321.5
22-Jul-05	4106.5	4615.9	0.0	0.0	1500	RH/RH MAGNETO	78.5	5606.5	22-Jul-10	1421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	1500	RH/LH MAGNETO	78.5	5606.5	22-Jul-10	1421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	1500	LH/RH MAGNETO	78.5	5606.5	22-Jul-10	1421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	500	RH/RH MAGNETO INSP	78.5	4606.5	22-Jul-10	421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	500	RH/LH MAGNETO INSP	78.5	4606.5	22-Jul-10	421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	500	LH/RH MAGNETO INSP	78.5	4606.5	22-Jul-10	421.5
22-Jul-05	4106.5	4615.9	0.0	0.0	300	VACUUM SYSTEM FILTER	4185.0	300.0		AR
03-Jul-74	1726.2	2235.6			2000	LEFT ENGINE VACUUM PUMP	4185.0	0.0		AR
					2000	RIGHT ENGINE VACUUM PUMP	4185.0	0.0		AR
					2000	N. GEAR RETRACT ROD ROD ENDS	2458.8	3726.2		AR
					2000	RETRACT MOTOR	4185.0	0.0		AR
					500	RETRACT MOTOR BRUSHES	4185.0	2000.0		AR
					5000	LANDING GEAR SELECTOR SWITCH	4694.4	500.0		AR
					2000	FLAP ACTUATORS	4185.0	4490.6		305.6
					2000	FLAP FLEX SHAFT	4185.0	2000.0		AR
					10	INST. AIR MAN. CHECK VALVE	4185.0	1000.0		AR
					1000	CABIN HEATER OVERHAUL	4185.0	1000.0		AR
					100	CABIN HEATER PRESSURE TEST	4185.0	100.0		AR
30-Nov-09	4185.0	4694.4			5	02 Tank Hydro test 5 Year	0.0	1000.0	30-Nov-14	AR
					1000	HEATER IGNITION VIBRATOR POINTS	4185.0	2000.0		AR
					2000	HEATER IGNITION VIBRATOR	4185.0	500.0		AR
					500	COMBUSTION BLOWER BRUSHES	4185.0	500.0		AR
					10	FUEL CELL FOAM INSERT - MAIN	4185.0	1500.0		AR
					1500	FUEL BOOST PUMP	4185.0	1500.0		AR
					1500	FUEL SELECTOR VALVE	4185.0	1500.0		AR
					10	FUEL CELL FOAM INSERT - AUX	4185.0	1500.0		AR
16-Feb-64	4185.0	4694.4			10	STATIC SYSTEM	0.0	0.0		AR
12-Jan-10	4185.0	4694.4			2	TRANSPONDER	0.0	0.0	Jan-12	AR
12-Jan-10	4185.0	4694.4			2	ALTITUDE INSPECTION	0.0	0.0	Jan-12	AR
08-Apr-10	4185.0	4694.4			1	ELT ANNUAL	0.0	0.0	Apr-11	AR
01-Apr-09	4185.0	4694.4			2	ELT BATTERY	0.0	0.0	Apr-11	AR
22-Jul-05	4106.5	4615.9	0.0	0.0	200	ENGINE AIR FILTER	78.5	4306.5		121.5
08-Apr-10	4185.0	4694.4			1	ANNUAL INSPECTION			08-Apr-11	
02-Dec-03	4185.0	4694.4			1	COMPAS SWING				
13-Nov-09	4185.0	4694.4			3000	WEIGHT AND BALANCE		3000.0		AR
13-Nov-09	4185.0	4694.4			100	AD 90-08-14 Wing spar cracks		4285.0		100.0
13-Nov-09	4185.0	4694.4			100	AD 89-05-02 Rt elevator fitting insp		4285.0		100.0
13-Nov-09	4185.0	4694.4			100	AD 64-10-03 Seat belt buckles		4285.0		100.0
13-Nov-09	4185.0	4694.4			2	AD 96-20-07 Heater pressure test		4285.0	13-Nov-11	100.0
13-Nov-09	4185.0	4694.4			100	AD 2007-08-08 Uplock Roller Lubrication		4285.0		100.0
13-Nov-09	4185.0	4694.4			100	AD 76-07-12 Bendix Ignition switch insp		4285.0		100.0
AIRCRAFT TT @ CHANGE TO HOBBS	509.4				DATE CHANGED	18-Dec-63	TIME ON HOBBS AT CHANGE	0.0		

Date 6-16-61

X - Installed in Airplane

O - Not Installed in Airplane

	<u>Item</u>	<u>Weight</u>	<u>Arm</u>
x	100. Propellers (2) Hartzell PHC-C3YF-2FU and spinner installations	86 ea	18
x	and (b) Woodward propeller governor (210355)	3 ea	26
o	(c) Beech unfeathering accumulator installation 96-960011	6 ea	68
x	101. Fuel Pumps		
	(c) Two electric booster pumps, Weldon 4032B	3 ea	89
	and (d) Two engine driven, CMC 626062-2	2 ea	55
x	102. Two Oil Radiators		
	(b) Harrison 8526732 or CMC 626189	5 ea	27
x	103. Two Carburetor Air Cleaners		
	(b) Air-Maze 122601	1 ea	61
x	104. Two Vacuum Pumps		
	(b) Garvin G-455	3 ea	56
x	105. Two Starters		
	(b) Delco-Remy 1108234 or CMC 627841	16 ea	55
x	108. Two 39-Gallon Auxiliary Fuel Tanks replacing Two Standard 25-Gallon Tanks	+11	75
x	201. Two Main Wheel-Brake Assemblies, 6.50-8, Type III		
	(c) Goodyear Wheel Assembly No. 9532135	8 ea	96
	Brake Assembly No. 9532475 or 9532412 or 9532679	5 ea	97
x	202. (b) Two main wheel side inflatable 6-ply tubeless tires	12 ea	96
x	205. One Nose Wheel, 5.00-5, Type III		
	(d) Goodyear Wheel Assembly No. 9532669	4	12
x	206. (b) One nose wheel 6-ply rating side inflatable tubeless tire used with Item 205.(c) only	6	12
x	210. Copilot Brakes	4	54
o	301. Generators		
	(d) Two 25-amp generators, Delco-Remy 1101911 or CMC 627274 and Two 25-amp regulators, Delco-Remy 1118976	19 ea	54
x	or (e) Two 40-amp generators, Delco-Remy 1105053 or CMC 628010 and Two 40-amp regulators, Delco-Remy 1119237c	26 ea	54
o	302. Battery		
	(a) One 24-volt, 17-amp-hr, Gill 12-GCAB-9	30	32
x	or (b) Two 12-volt, 24-amp-hr, Reading S24	21 ea	32
o	or (c) Two 12-volt, 24-amp-hr, Sonotone 22321 installed per Beech Dwg 95-001031	17 ea	32
x	303. Two Landing Lights		
	(a) General Electric 4523 or 4553	1 ea	75
x	304. Paralleling Relay		
	(a) Delco-Remy 1116902 or Lycoming 71349	1	49

Serial No. TC-157
Registration No. N1357Z
Date 6-16-61

BEECHCRAFT MODEL 95-55
EQUIPMENT LIST

Page 2

X - Installed in Airplane

O - Not Installed in Airplane

	<u>Item</u>	<u>Weight</u>	<u>Arm</u>
x	401. DMCB Approved Airplane Flight Manual (k) Model 95-55 dated November 2, 1960 latest revision		
x	402. Heater Installation (a) Beech 95-550001 cabin heater installation	45	19
	404.(c) Dual Control Column (T-type) Beech 95-524034-3 or -5	3	72
x	501. Propeller Anti-Icer (b) 3-gallon fluid tank, pump and lines Fluid Arm 33 (Includes 22 pounds of fluid)	31	+35
	503. Surface De-Icers (c) Goodrich Type (Per Beech Dwg 95-970000- 129) (Weight Includes 7 pound air charged at 3000 psi)	66	75
x	601. Stall Warning Indicator - Safe Flight	1	58
x	602. Heated Pitot Head Installation	1	75
x	603. (b) Optional Seating Arrangement (5th Seat) 95-534022	20	153
	604. Autopilot Installation (c) Tactair T-3 per Beech Drawing MCO B54453 (d) Altitude Hold per Beech Drawing MCO B54453-15	13 2	145 58
	606.(a) Scott High Pressure Oxygen Installation per Beech Drawing MCO B49061	38	30
	(b) Zep High Pressure Oxygen Installation per Beech Drawing 96-560000 (38 cu. ft.)	32	178
x	(c) Zep High Pressure Oxygen Installation per Beech Drawing 95-560000-1X (48 cu. ft.) 001059	39	180
	<u>SPECIAL EQUIPMENT</u>		
	Executive Table (Stowed)	3	101
x	Instrument Post Light	1	68
x	Nose Taxi Light	2	-9
x	Rotating Beacon Dual	4	142
	Rotating Beacon	2	182
x	External Power Receptacle	2	77
x	Headrest	1	Var.
x	2 Rear Seats Standard	20 ea.	126
x	Cabin Speaker	2	102

Serial TC-157
Registration N1357Z
Date 6-16-61

BEECHCRAFT MODEL 95-55
EQUIPMENT LIST

Page 3

RADIO EQUIPMENT

Item	Weight	Arm
<u>Collins 17L-8 & 51X-3 VHF</u>		
x 17L-8 Transmitter	2	63
x 51X-3 Receiver <i>REMOVED 6-16-61</i>	3	63
x Power Supply and Mount	7	42
x Omni Antenna and Lead In	1	190
x Transmitter Antenna and Lead In	1	190
x Microphone and Headset	1	68
x Wiring, Plugs, Etc.	3	55
x Baggage Compartment Webbing	1	40
x 344D-1 Omni Converter <i>REMOVED 6-16-61</i>	3	63
x Collins 618F-1 Transc.	5.6	63
x Collins 427D-1 Power Supply	7.2	54
x Collins 51X-3 Receiver <i>REMOVED 8-3-77</i>	2.9	63
x Collins 344D-2 Omni-Conv.	2.4	63
x Motorola, A.D.F. T-12	5.0	63
x Motorola A.D.F. Indicator	1.5	63
x A.D.F. Loop	1.3	165
x A.D.F. Sense Ant.	.5	122
x M.B.T.-24 Marker Beacon	1.2	54
x Collins 37X-2 Marker Antenna	.7	167.5
x Collins 427-B1 Power Supply	6.0	55
x A.D.F. Amplifier	1.7	68
X Winterization Kit #55-13-1	2.0	24
X Glideslope Receiver (Narco)	4.7	55
X Airspeed Indicator	.75	67
X Directional Gyro <i>REMOVED 8-3-77</i>	4.75	64
X Gyro Horizon	4.90	64
X Glideslope Antenna	Negligible	
X Fittings, Tubing, Etc.	1.00	60
X Prop Anti-icer Kit	9.00	40
X Anti-icer fluid, 3 gallons	22.00	33
X NARCO AT50A Transponder	3.0	63
X KING KX170A Transceiver	7.00	63
X KING KI 211B Omni Converter	3.00	63
X KING KMA 20 Audio Panel	2.3	64
X KING KA 39 Power Converter	1.1	54
X KING KX170B Nav Com	7.0	63
X KING KI209 ILS Indicator	1.2	65
X KING KN73 Glide Slope Receiver	2.5	54
X KING KA39 Power Converter	1.1	54
X King KN 64 DME	2.5	64

AIRFRAME APPLIANCES

A/C REG. #N1357Z
 MODEL #..... Baron 95-55
 SERIAL #..... TC-157
 YEAR 1961

*this list compiled on
 07 OCT 2008 @ TT 4694.4

AIRFRAME APPLIANCES

Install Date Airframe TT	Component	Manufacturer	Part/Model Number	Serial Number	Removal Date Airframe TT
	LH Vacuum Pump	Weston	G455	18529	
	ELT	Ameri-King Corp.	450001	462811	
	Ignition Switch (LH / RH)	Bendix	10-126630-18		
	Fire Extinguisher	Amerex Corp.	344	U-796753	
	Seat Belt Restraints	Davis Aircraft Products	FDC-2700 series		
	RH Brake Disc	Cleveland			
	RH Brake Caliper	Cleveland	30-60	8891	
	RH Wheel Halves	Cleveland	7.00 x 8 4098A		
	Strobe Light Top	Flight Strobe/ Universal Corp.	4400	155644	
	Strobe Light Bottom	Flight Strobe/ Universal Corp.	4400	155647	
	Voltage Converter 28v to 14v	Narco Avionics	MP-16 Class II	12161	
	Combustion Heater Unit	Janitrol	D83A28	0627	
	Main Vacuum Regulator	*original			
	Airspeed Switch	Bishop Aviation Inc.	S-1498-2		
	Oxygen Cylinder				
	LH Vacuum Regulator	Garwin	32-436	4709	
	RH Aux Fuel Pump	Weldon Tool Co.	4032B	73623	

AIRFRAME APPLIANCES

A/C REG. # N1357Z
 MODEL # Baron 95-55
 SERIAL # TC-157
 YEAR 1961

*this list compiled on
 07 OCT 2008 @ TT 4694.4

AIRFRAME APPLIANCES

Install Date Airframe TT	Component	Manufacturer	Part/Model Number	Serial Number	Removal Date Airframe TT
	Air Filter LH	Brackett	BA-7610		
	Air Filter RH	Brackett	BA-7610		
	12v Battery 1	Concorde	RG-25XC	40114626	
	Fuel Selector Valve RH		HE825-1		
	Fuel Selector Valve LH		HE825-2		
	Fuel Cell RH Main				
	Fuel Cell LH Main				
	RH Vacuum Pump	WESTON	G455	74981	
	LH Prop. Spinner	Hartzell	C-3567-1		
	RH Prop. Spinner	Hartzell	C-3567-1		
	LH Brake Disc	Cleveland			
	LH Brake Caliper	Cleveland	30-60		
	LH Wheel Halves	Cleveland	7.00 x 8 4098A		
	RH Vacuum Regulator	Garwin	32-436	3666	
	12v Battery 2	Concorde	RG-25XC	40114626	
	Combustion Heater Ignition Unit	Janitrol	11C30	6711038	

AIRFRAME APPLIANCES

A/C REG. #N1357Z
 MODEL # Baron 95-55
 SERIAL # TC-157
 YEAR 1961

*this list compiled on
 07 OCT 2008 @ TT 4694.4

AIRFRAME APPLIANCES

Install Date Airframe TT	Component	Manufacturer	Part/Model Number	Serial Number	Removal Date Airframe TT
	Combustion Heater Compressor	Dynamic Air Engineering	M4861H-1A	786	
	Continuous Flow Oxygen Regulator	Alak Products Inc.	A2000	6971	
	RH Eng. Voltage Regulator	Delco-Remy	1119237E		
	LH Eng. Voltage Regulator	Delco-Remy	1116902		
	Nose Gear Taxi Light Kit	Beech	55-360027		
	LH Aux Fuel Pump	Weldon Tool Co.	4032B	4138	
	Stall Warning Indicator	Safe Flight	151	64980	
	Dual Control Column (T-Type)	Beech	95-524034-3		
	RH & LH Vent Windows	Beryl D'Shannon Aviation Specialties Inc.	B-1308(-1)(-2)		
	LH / RH Prop. Anti-Ice Slinger Ring Kit	Beech	IPC P/N 96-960006-27		
	Polyurethane Prop. Tape	Prop-Guard Aerospace Inc.	LEI 4359-1		
	Extended Nose Cone	Beech	796-410021-613 IPC P/N 96- 410021-609		
	Nose Gear Taxi Light	General Electric	4553		

POWER PLANT APPLIANCES
 LH ENGINE MODEL #.....Con. IO-470-L
 SERIAL #.....CS-155839-8-L

A/C REG. #N1357Z
 MODEL #.....BARON 95-55
 SERIAL #.....TC-157
 YEAR 1961

POWER PLANT APPLIANCES					
Install Date Airframe TT	Component	Manufacturer	Model Number	Serial Number	Removal Date Airframe TT
	Fuel Pump	Continental(?)	638156-3		
	Flow Divider	Continental	631427-1	M2419	
	Oil Cooler	Modine	IE326	02 65	
	Injectors	General Aviation Modifications, Inc. GAMIjectors	GF 118 GM 126 GA 142	1190	
	Generator	Aerotech (Delco-Remy)	1105056	A504078	
	Starter	Aerotech (Prestolite)	MHJ 4003	12D000066	
	RH Magneto	Bendix	BL-600656-1 (S6RSC-205)	E04JA002R	
	LH Magneto	Bendix	BL-600606-1 (S6RSC-201)	E03IA093R	
	RH Ignition Harness	<i>Bendix</i>	CH11730		
	LH Ignition Harness	<i>Bendix</i>	CH11730		
	Upper Vacuum Pump	Weston	G455	18529	
	Tach Generator	Jack & Heintz	AN5547 2	51-01562	
	Propeller Governor	Woodward	B210438	667414	
	Propeller	Hartzell	PHC-C3YF-2UF		
	Propeller Hub	Hartzell		EB544	
	Propeller Blades	Hartzell	FC7663-2R	C92225 C94697 C94730	

POWER PLANT APPLIANCES
 RH ENGINE MODEL #.....Con. IO-470-L
 SERIAL #.....CS-91949-5-L

A/C REG. #N1357Z
 MODEL #.....BARON 95-55
 SERIAL #.....TC-157
 YEAR.....1961

POWER PLANT APPLIANCES					
Install Date	Component	Manufacturer	Model Number	Serial Number	Removal Date
Airframe TT					Airframe TT
	Fuel Pump	Continental(?)	638156-3		
	Flow Divider	Continental	631427-1	631427	
	Oil Cooler	Modine	IE1104D	02 1	
	Injectors	General Aviation Modifications, Inc. GAMIjectors	GF 118 GM 126 GA 142	1191	
	Generator	Aerotech (Delco-Remy)	11050 56	A505015	
	Starter	Aerotech (Delco-Remy)	1108234	74390	
	RH Magneto	Bendix	BL-600656-1 (S6RSC-205)	E04JA007R	
	LH Magneto	Bendix	BL-600606-1 (S6RSC-201)	E031A100R	
	RH Ignition Harness	<i>Bendix</i>	CH11730		
	LH Ignition Harness	<i>Bendix</i>	CH11730		
	Upper Vacuum Pump	Weston	G455	74981	
	Tach Generator	Globe	22A553	C172	
	Propeller Governor	Woodward	210355JFRSAA	582364	
	Propeller	Hartzell	PHC-C3YF-2UF		
	Propeller Hub	Hartzell		EB545	
	Propeller Blades	Hartzell	FC7663-2R	C94716 C94728 C94712	

AIRFRAME AD INDEX

A/C Reg. Number.....N1357Z
Model Number.....95-55
Serial Number.....TC-157
Year 1961

AIR WORTHINESS DIRECTIVE INDEX							
Date Index Compiled on							
Effective Date	Related	Subject	N/A &	One	Recurring		Remarks
AD Number	SB's		Reason	Time	X	Time	
Eff Date: 27-OCT-1967 AD 67-29-01		Rudder Spar Web		X			
Eff Date: 09-JUL-1970 AD 62-08-03		Control Wheels		X			
Eff Date: 05-JAN-1972 AD 72-01-02		Oil Drain Tubes	N/A Tubes not installed				
Eff Date: 20-MAY-1972 AD 72-11-02		Engine Fuel Interruption	N/A No Gaskets	X			SEE Log Entry Dated 4-8-2018
Eff Date: 26-DEC-1973 AD 73-26-08		Roll and Pitch Servo Clamps	N/A Auto pilot not installed				
Eff Date: 05-FEB-1974 AD 68-26-06		Placard installation		X			
Eff Date: 23-JUN-1975 AD 75-13-02	Beech 0723-241 Hartzell 107A	Propeller blade vibration	N/A by model/sp				
Eff Date: 06-AUG-1975 AD 75-16-10		Elevator trim tab		X			
Eff Date: 30-JUN-1978 AD 78-05-06		Goodyear fuel cells	N/A by Manufacturer	X			SEE Log Entry Dated 4-8-2010
Eff Date: 25-MAY-1984 AD 84-09-01		Window emergency egress provision	N/A due to max seating				
Eff Date: 24-MAR-1989 AD 89-05-02		Magnesium elevator control fittings		X	X RH only		LH is Aluminum RH is Magnesium
Eff Date: 07-MAY-1990 AD 90-08-14	2269R1	Wing spar structure			X	100hr	Check Recommended
Eff Date: 25-NOV-1991 AD 91-17-01		Elevator trim tab actuators		X			
Eff Date: 02-SEPT-1997 AD 97-14-15		Cabin side door and utility door handle		X			
Eff Date: 05-JUL-2000 AD 99-05-13R1wd		Withdrawal of AD 99-05-13	Withdrawn				
Eff Date: 13-DEC-2001 AD 2001-23-10		Flap flex shaft assembly	N/A by manufacture date				
Eff Date: 25-MAY-2007 AD 2007-08-08	Service Instructions Beechcraft 0448-211	Uplock roller			X	100hr	Supersedes 72-22-01
Eff Date: AD							
Eff Date: AD							
Eff Date: AD							
Eff Date: AD							

A/C Reg. Number N1357Z
Model Number 95-55
Serial Number TC-157
Year..... 1961

[illegible]

A/C REG. #.....N1357Z
MODEL #95-55
SERIAL #.....TC-157
YEAR.....1961

DUE EVERY 100 Hrs

RECURRING A.D. COMPLIANCE RECORD

U:\Maintenance Records\Beech Baron\N1357Z\AIRFRAME\Airframe AD's\AF AD recurring 89 05 02.doc

A/C Reg. Number N1357Z
Model Number 95-55
Serial Number TC-157
Year..... 1961

[illegible]

A.D. 2007-08-08

Due Every: 100 hrs

Subject: Uplock Roller Lubrication

Related SB: Beechcraft S.I. 0448-211, Rev 1

RECURRING A.D. COMPLIANCE RECORD

[illegible]

AIRFRAME

Model Number.....95-55

Serial Number..... TC-157

Year 1961

Mfg....Teledyne Continental Motors
Model Number.....IO-470-L
Serial Number.....CS 155839-8-L
(Left)

[illegible]

AIRFRAME

A/C Reg. Number.....N1357Z
Model Number.....95-55
Serial Number.....TC-157
Year.....1961

[illegible]

[illegible]

AIRFRAME

Model Number.....99-55

Serial Number.....TC-157

Year 1961

Mfg.Hartzell
Model Number.....PHC-C3YF-2UF
Serial Number.....EB545
(Right)

[illegible]